



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI20010163/Etd3e2

3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

Date : 16-10-2020



Code : GAI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	XE 3831M	<b>Veh. Inspected</b>	SBS 6311P
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CLMOMVC000003891	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	SHERY WONG	<b>Assign Date</b>	22/09/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES BENZ CITARO O530	<b>c.c</b>	6374
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2012
<b>Chassis No.</b>	WEB62808323123778	<b>Colour</b>	MULTI COLOUR
<b>Odometer</b>	479058	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	295/80 R22.5	BRIDGESTONE	5 mm
<b>L/H Front Tyre</b>	295/80 R22.5	BRIDGESTONE	5 mm
<b>R/H Rear Tyre</b>	295/80 R22.5 (D)	BRIDGESTONE	5/5 mm
<b>L/H Rear Tyre</b>	295/80 R22.5 (D)	BRIDGESTONE	5/5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	19/09/2020	<b>Inspection Date</b>	23/09/2020
<b>Survey held at</b>	TOWER TRANSIT SINGAPORE PTE. LTD. 21 BULIM DRIVE SINGAPORE 648170		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**