



ACE AUTOLUTION PTE LTD
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel: 6702 4282 Fax: 6702 4202

TP AIG Quiling

Page No. 1

JmYSRCY2AA4001640

Vehicle No. SJY1236E MITSUBISHI LANCER

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	REAR BOOTLID <i>Dented</i> ✓		794 ✓	
2	REAR BOOTLID HINGE LH & RH @\$75.00 <i>new x</i>		150 X	
1	REAR BOOTLID "LANCER" EMBLEM <i>2</i>		45 ✓	
1	REAR BOOTLID "GLX" EMBLEM <i>free</i> ✓		48 ✓	
1	REAR BOOTLID MRK THREE DIA		42 ✓	
1	REAR BOOTLID TOP LOCK <i>Dented</i> ✓		98 ✓	
1	REAR BOOTLID LOWER LOCK <i>new</i> x		57 X	
2	REAR BOOTLID STOPPER LH & RH @\$ <i>new</i> x		36 X	
1	REAR BOOTLID WEATHERSTRIP <i>lit</i> ✓		186 ✓	
2	REAR BOOTLID LAMP LH & RH @\$ <i>new</i> x		348 X	
1	REAR BOOTLID REFLECTOR <i>new</i> x		348 X	
1	REAR BUMPER <i>Dented</i> ✓		747 ✓	
2	REAR BUMPER SIDE RETAINER LH & RH @\$ <i>new</i> ✓		30 ✓	
1	REAR BUMPER CENTRE BEAM <i>best</i> ✓		273 ✓	
2	REAR TAIL LAMP LH & RH @\$ <i>cracked</i> ✓		790 ✓	
2	REAR TAIL LAMP PANEL LH <i>parts</i> x		145 X	
2	REAR FENDER LH <i>parts</i> x		895 X	
2	REAR FENDER INNER COWLING LH & RH @195.00 <i>new</i>		390 X	
2	REAR FENDER AIR VENT LH & RH @\$88.00 <i>new</i> x		176 X	
1	REAR FENDER INNER TRIM LH & RH @\$ <i>torn</i> ✓		508 ✓	
1	REAR END PANEL <i>Dented</i> ✓		545 ✓	
1	REAR END PANEL TOP GARNISH <i>Dented</i> ✓		144 ✓	
1	REAR SPARE TYRE PANEL <i>parts</i> x		776 X	
1	REAR SPARE TYRE PANEL TOP BOARD <i>torn</i> x		187 ✓	
1	REAR SPARE TYRE PANEL BOLT <i>new</i> x		35 X	
1	REAR ANTENNA KEYLESS <i>new</i> x		142 X	
1	REAR DOOR LH <i>new</i> x		934 X	
2	Rear Number Plate Lamp <i>cracked</i> 78 ✓		0.00	
2	Rear Bumper Reflector <i>cracked</i> 138 ✓		0.00	
		10%	0.00	10%
			0.00	
	SPECIAL ITEMS			
1 SET	REAR BUMPER CLIPS <i>new</i>		100.00	30
1	REAR FENDER SEALANT <i>3 new</i>		100.00	X
1	REAR WINDSCREEN SEALANT		80.00	X
1 SET	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		100.00	10
1	REAR WINDSCREEN INNER SEAL <i>new</i>		70.00	X 240
1 SET	REVERSE SENSOR <i>Dented</i>		280.00	20
	Total Parts		730.00	

4693
4223.70

**ACE AUTOLUTION PTE LTD**

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SJY1236E MITSUBISHI LANCER

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	OUR ASSESSMENT (\$)
	LABOUR		
1	To remove and panel beat the affected parts & fittings to commence repairs and replace damaged parts	1800.00	1200.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	1300
3	To remove and refix wiring at damaged areas	180.00	30
4	To perform anti rust treatment on affected areas	150.00	60
5	To remove & replace reverse sensor and check for proper functions	120.00	50
6	To remove & refix / replace rear trims , garnish and fittings so as to facilitate repairs as rear compartment	180.00	80
			2780.
8	To conduct water seepage test	120.00 x	
9	To transfer rear boot mechanism	150.00	80
	Labour Total :	4300.00	
	TOTAL (PARTS & LABOUR):	5030.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
L/s 23/09/20

07 Days-

Total: 724370

L/s: 5.8K.

6.4K
5.8K.