

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jenny Lew

Date: 19 Oct 2020

## **Preliminary Advice**

Insured Vehicle No	: PC5210Y		
TP Vehicle No	: SJJ2697E	Accident Date	: 10/09/2020
Make	: HONDA FIT	Assignment Date	: 22/09/2020
Date of Inspection	: 30/09/2020	Est. Duration of Repair	: 6
Inspection At	: DYNAMIC AUTOWORK PTE. LTD (HQ) 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,717.04
Revised Amount	:S\$	5,992.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,992.80

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted without "prejudice" basis.