



KGC WORKSHOP PTE LTD

Since 1967
Sincere • Secure • Satisfactori

Not Authorised
LLP &
Recurry After Paint
5 days

KGC WORKSHOP
Sincere • Secure • Satisfaction
14 Ang Mo Kio St.63, Block B (S) 569116
Tel : 6453 6279 / 6456 5410
Email : contact@kgcworkshop.com.sg

Yew Kai Long
14 Ang Mo Kio St 63
Block B
Singapore 569116

TP
Date: 10/9/2020
No of Page: 1/1

Registraion No : SFP 9889M
Accident Date : 21-Sep-20
Our Ref : TP

Model : VW SHARAN 2.0 TSI 7N24MY
Chassis No: WVVZZZ7NZKV006781
Engine Capacity 2.0cc

S/No	Qty	Items	Unit Price	Amount	
1	1	Rear Fender RHS	\$ 1,450.00	\$ 1,450.00	✓
2	1	Rear Fender Inner Shield RHS	\$ 220.00	\$ 220.00	X
3	1	Rear Bumper	\$ 1,050.00	\$ 1,050.00	✓
4	1	Rear Bumper Retainer	\$ 52.00	\$ 52.00	X
5	1	Rear Reflector RHS	\$ 65.00	\$ 65.00	X
6	1	Rear Lower Arm RHS	\$ 385.00	\$ 385.00	X
7	1	Rear Shock Absorber RHS	\$ 375.00	\$ 375.00	X
8	1	Rear Kunckle Arm, Bearing, Hub RHS	\$ 625.00	\$ 625.00	X

\$	4,222.00
-10%	\$ 422.20
Total for spare parts	\$ 3,799.80

Special Nett

1	1 set	RHS Fender Clips	\$ 50.00	\$ 50.00	X
2	1 set	Rear Bumper Clips	\$ 50.00	\$ 50.00	✓
3	1	RHS rear Rim	\$ 800.00	\$ 800.00	X
4	1	RHS rear tyre	\$ 150.00	\$ 150.00	X
5	1set	Revese Sensor	\$ 380.00	\$ 380.00	X

Total for SP	\$ 1,430.00
Sub-Total for Parts :	\$ 5,229.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfactori

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts		1,200.00 <i>600l</i>
2		To putty and spray paint on all accident damage parts and other accident		1,200.00 <i>640l</i>
3		To remove and refit reverse sensor		80.00 <i>50l</i>
4		To perform Wheel Alignment		<i>na</i> 80.00 <i>X</i>
5		To remove and refit undercarriage to facilitate repair		<i>na</i> 300.00 <i>X</i>
6		To check wiring system to facilitate repair and refit the same		100.00 <i>20l</i>
7		Apply rust proofing on the adjacent panels		50.00 <i>30l</i>

TOTAL AMOUNT : 3,010.00
OVERALL COST : 8,239.80