

VZM NO: FBA 7100 U

CHASSIS No: 5YWD45000

DOA: 11 Aug 20

TP LonPac.
Denise.

01/ps REAR fender	unld	125 ✓
01/ps " rim	NEW	95 X
01/ps " tyre		70 X
01/ps " Number plate	Ref	30 SN ✓
01/ps " " holder	wt	25 ✓
01/ps " Taillamp	unld	175 95.
01/ps " " garnish	unld	85 ✓
01/ps " " side garnish	unld	115 ✓
01/ps LEFT handle holder	Dryd	40 ✓
01/SET Rear side mirror	NEW	100 X
01/ps front Brake lever (LH)		75 ✓
01/ps side stand (LH)	wt	55 ✓

615
Len 10% 553.50
S.N. 30

Labour

To supply labour to replace above mentioned parts ~~450~~ 200
To supply labour & paint to spray accident affected area ~~550~~ 200
To supply labour to rewire the replace parts ~~60~~ 20.

420.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 1003.50
L/s 500 ✓
(Nett Value)
04 Days.