



TRANS EUROKARS PTE LTD
5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

24 SEPTE 1400-h
EUROKARS GROUP

not Authorized
DATE: 22-Sep-20
Main
Whaph to before painting
5 days.

LONPAC INSURANCE BHD LKK 300 BEACH ROAD #17-04/07 THE CONCOURSE Singapore 199555 ATTN.: MOTOR CLAIMS FAX:	NAME: Mr Hao Yutao ADDRESS: Blk 331 Sembawang Close #12-363 Singapore 750331 TEL: 91824068	WIP: 36853 EXCESS: TBC DATE: 22-Sep-20
VEH NO: SKW3099U	DATE IN:	CONTACT PERSON: RONALD
CHASSIS NO: JM6BP2HAAK1102352	MILEAGE:	TYPE OF CLAIM: 3RD PARTY CLAIMS
MODEL: MAZDA3	DATE REG.: 31-Jan-20	POLICY NO.:

NATURE OF WORKS

Parts Description				REVISED	PRICES	
NO	QTY					
1	REAR BUMPER	1	MBCKN-50-221BBB	DD	\$ 520.40	✓
2	BUMPER,REAR LOWER	1	MBCKR-50-222B	DD	\$ 711.20	✓
3	BRACKET,BUMPER	1	MKD53-50-251	DD	\$ 5.40	✓
4	STAY,REAR BUMPER	1	MBCKN-50-291A		\$ 126.70	?
5	RETAINER(R),REAR BUMPER	1	MBCKN-50-2H1		\$ 34.70	?
6	RETAINER(L),REAR BUMPER	1	MBCKN-50-2J1B	11	\$ 34.70	X
7	S/SPLASH RHR BUMPER	1	MBENC-50-340	11	\$ 60.80	X
8	SHIELD(L),SPLASH	1	MBCKN-50-350	11	\$ 63.90	X
9	FASTENER	4	MBHN1-50-0Z1A	11	\$ 10.80	X
10	FASTENER	4	MBCKA-50-0Z1	11	\$ 9.60	X
11	COVER(R),TOWING HOOK BP	1	MBCKN-50-EK1	DD	\$ 9.10	✓
12	COVER(L),TOWING HOOK BP	1	MBCKN-50-EL1	11	\$ 9.10	X
13	REFLECTOR(R),REFLEX-REAR	1	MGRF5-51-5L0A		\$ 41.20	?
14	REFLECTOR LHR REFLEX-GL3	1	MGRF5-51-5M0A	11	\$ 41.10	X
15	REINF.,REAR BUMPER BP	1	MBCJH-50-260	.	\$ 541.70	?
16	CLIPS	10	MBGV4-56-145	DD	\$ 29.00	✓
17	FASTENERS	6	MB45A-56-146A	DD	\$ 18.00	✓
18	TAILGATE	1	MBDY0-62-02XA	DD	\$ 1,214.30	✓
19	WEATHERSTRIP	1	MBDMT-62-761	11	\$ 154.90	X
20	FASTENER	7	MKD45-68-865	DD	\$ 18.90	✓
21	FASTENER	4	MGJ21-68-885B02	DD	\$ 12.00	✓
22	TRIM,LIFTGATE-LOWER BP	1	MBCKD-68-960A02	11	\$ 267.30	X
23	TRIM,LIFTGATE-UPPER BP	1	MBCKD-68-930A02	11	\$ 106.90	X
24	TRIM(R)/GATE -SIDE HB BP	1	MBCKD-68-940A02	11	\$ 51.70	X
25	TRIM(L)/GATE -SIDE HB BP	1	MBCKD-68-950A02	11	\$ 51.70	X
26	TAILLAMP LH	1	MB0L6-51-160	11	\$ 933.70	X
27	TAILLAMP RH	1	MB0L6-51-150	SCR	\$ 933.70	✓
28	LAMP TAILGATE LH	1	MBCKD-51-3G0	11	\$ 630.60	X
29	LAMP TAILGATE RH	1	MBCKD-51-3F0	CNE	\$ 630.60	✓
30	SENSOR FRT BUMPER BP	4	MB0J8-67-UC1 64	11	\$ 760.00	X

31	SENSOR,ULTRASONIC BP	2	MB0J9-67-UC1	11	\$ 380.00	X
32	BRACKET B/SENSOR BP	6	MB0J8-67-UC6	11	\$ 140.40	X
33	TAPE,PROTECTOR	3	MBCKA-50-EM1	11	\$ 14.10	X
34	CORD SHORT	1	MBCKP-67-A20B	11	\$ 552.20	X
35	RETAINER SENSOR	1	MB0L3-67-UC5 SY		\$ 47.20	7
36	RETAINER SENSOR	1	MB0L4-67-UC5 SY		\$ 47.20	7
37	RETAINER SENSOR	1	MB0L5-67-UC5		\$ 47.20	7
38	RETAINER SENSOR	1	MB0L6-67-UC5		\$ 47.20	7
39	RETAINER SENSOR	1	MB0M4-67-UC5 SY		\$ 47.20	7
40	RETAINER SENSOR	1	MB0M3-67-UC5 SY		\$ 47.20	7
41	MONITOR,BLIND SPOT	2	MB0J9-67-Y30C	11	\$ 3,601.40	X
42	PROTECTOR TAILGATE (1)	3	MBEMD-51-954	11	\$ 35.10	11
43	PROTECTOR TAILGATE (2)	2	MBEMD-51-9B5A	11	\$ 36.40	11
44	PROTECTOR TAILGATE (3)	4	MBEME-51-979	11	\$ 36.40	11
45	PROTECTOR TAILGATE (74)	7	MBEMF-51-954	11	\$ 102.20	11
46	PROTECTOR TAILGATE (5)	1	MBEME-51-954A	11	\$ 9.10	11
47	CLIP, TAILGATE	2	MKB8A-51-SJ3	11	\$ 11.00	11
48	FASTENER, TAILGATE	7	MKB8A-51-W24A	11	\$ 25.90	11
49	CLIP, TAILGATE	1	MGB02-67-014	11	\$ 6.60	11
50	CLIP, TAILGATE	2	MTK78-51-0B6	11	\$ 22.00	11
51	ORNAMENT HB REAR BP	1	MBCKD-51-721	11	\$ 33.00	11
52	ORNAMENT RR HB BP	1	MBCKD-51-771A	11	\$ 40.50	11
53	MASCOT REAR BP HB	1	MBDMT-51-730F	11	\$ 455.60	11
TOTAL PARTS					\$ 13,818.80	
TOTAL PARTS COST					\$ 13,818.80	

Labour Description				
	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1320	\$	1,980.00
	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.	1260	\$	1,890.00
	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		\$	560.00
	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	11	\$	120.00
	TO TRANSFER REVERSE SENSORS.	180	\$	330.00
	TO TRANSFER REVERSE CAMERA	180	\$	330.00
	TO TRANSFER TAILGATE MECHANISMS.	300	\$	660.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE Page 2 of 3

Acknowledged by Repairer

Signature:

Date:

MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	11 X	\$	250.00
MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$	250.00
MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$	350.00
	TO SUPPLY BRILA PREMIUM COATING.	11	NETT	\$ 350.00 X
MZ-BR-SUNDRI	SUNDRIES.	net 20	NETT	\$ 100.00
		TOTAL LABOUR	\$ -	\$ 7,170.00
		TOTAL PARTS	\$ -	\$ 13,818.80
		TOTAL	\$ -	\$ 20,988.80
		LESS EXCESS	\$ -	\$ -
		TOTAL AFTER EXCESS	\$ -	
		GST 7%	\$ -	\$ -
		GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature