

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0677/2020/NS
DATE	:	18-Sep-20
WIP	:	49924

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR YIP CHEEN PHANG(YE ZHANPENG)
ADDRESS	:	BLK 277 CHOA CHU KANG AVE 2 #04-317 SINGAPORE 680277
TELEPHONE	:	HP +65 97975552
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2100440289-04
VEHICLE NO	:	SKK 7751 G
MODEL CODE	:	AUDI A4 1.8T FSI MU 8K203
MODEL YEAR	:	28/11/2015
ENGINE NO	:	CJE 115111
CHASSIS NO	:	WAUZZZ8K4FA183961
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	17-Sep-20
PLACE OF ACCIDENT	:	51 BUKIT BATOK CRESCENT UNITY CENTRE

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKK 7751 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00 ✓	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00 1000	✓
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$ 3,000.00 1100	✓
5	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N \$ 384.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 6,114.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 7751 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER <i>Rebnd.</i>	\$	2,278.00	✓	1822.40
2 FRONT BUMPER FIXING PARTS <i>Neu</i>	\$	256.00	+	
3 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Neu</i>	\$	225.00	+	
4 FRONT BUMPER GRILLE - LOWER CENTRE <i>3 Neu</i>	\$	134.00	+	
5 FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	\$	192.00	+	
6 FRONT BUMPER SUPPORT ELEMENT - UPPER <i>Neu</i>	\$	59.00	+	
7 RADIATOR GRILLE <i>Not Neu</i>	\$	1,077.00	+	
8 FRONT BUMPER VENT GRILLE - RH <i>Neu</i>	\$	134.00	+	
9 FRONT WHEEL SPOILER - RH <i>Neu</i>	\$	51.00	+	
10 FRONT BUMPER GUIDE SECTION - RH <i>Not Neu</i>	\$	36.00	? X	
11 FRONT FENDER - RH <i>Dented</i>	\$	979.00	✓	782.80
12 FRONT FENDER ATTACHMENT PARTS <i>Not Neu</i>	\$	57.00	2X	
13 FRONT FENDER BRACKET - RH <i>Not Neu</i>	\$	52.00	? X	
14 DEFORMATION ELEMENT BRACKET-RH REAR <i>Neu</i>	\$	49.00	+	
15 FRONT FENDER BRACE - RH LOWER <i>Bent.</i>	\$	117.00	? 93.60	
16 WHEEL HOUSING LINER <i>Not Neu</i>	\$	237.00	+	
17 WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not Neu</i>	\$	44.00	+	
18 STONE CHIP GUARD <i>Neu</i>	\$	72.00	✓	57.36
19 ADHESIVE TAPE <i>Not Neu</i>	\$	54.00	? X	
20 HEADLIGHT MOUNTING - RH <i>Not Neu</i>	\$	117.00	✓ X	93.60
SUB TOTAL SPARE PARTS	:	\$ 6,220.00		

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 7751 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 HEADLAMP BRACKET - RH <i>Not ne</i>		\$	105.00	<i>x</i>
22 HEADLIGHT - RH <i>cracked</i>		\$	2,316.00	<i>✓ 1852.80</i>
23 GAS DISCHARGE LAMP <i>Not Ne</i>		\$	408.00	<i>x</i>
24 DAY DRIVING LIGHTS POWER MODULE <i>Not ne</i>		\$	538.00	<i>x</i>
25 GAS DISCHARGE LAMP CONTROL UNIT		\$	1,084.00	<i>x</i>
26 RETAINING PLATE - RH <i>Not ne</i>		\$	24.00	<i>x</i>
27 HEADLIGHT HOSE - RH		\$	36.00	<i>x</i>
28 HALOGEN FOG LAMP - RH <i>Not ne</i>		\$	259.00	<i>x</i>
29 LIFT CYLINDER - RH <i>Not ne</i>		\$	208.00	<i>x</i>
30 FRONT NO PLATE <i>Not ne</i>	S/N	\$	60.00	<i>x</i>
31 SUNDRIES <i>Ne</i>		\$	<i>✓ 300.00</i>	<i>? 10.24</i>
TOTAL SPARE PARTS	:	\$	11,558.00	
TOTAL LABOUR CHARGES	:	\$	6,114.00	
GRAND TOTAL	:	\$	17,672.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *22/09/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.* *5 days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0677/2020/NS
DATE : 18-Sep-20
WIP : 49924

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

5 days - ok - Jy - 3 Dec 20

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR YIP CHEEN PHANG(YE ZHANPENG)
ADDRESS : BLK 277 CHO A CHU KANG AVE 2
#04-317
SINGAPORE 680277
TELEPHONE : HP +65 97975552
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100440289-04
VEHICLE NO : SKK 7751 G
MODEL CODE : AUDI A4 1.8T FSI MU 8K203
MODEL YEAR : 28/11/2015
ENGINE NO : CJE 115111
CHASSIS NO : WAUZZZ8K4FA183961
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Sep-20
PLACE OF ACCIDENT : 51 BUKIT BATOK CRESCENT UNITY CENTRE

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKK 7751 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECH AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 280.00	\$	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N	\$ 350.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 2,100.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.		\$ 3,000.00	\$	1,100.00
5	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N	\$ 384.00	\$	384.00
TOTAL LABOUR CHARGES		:	<u>\$ 6,114.00</u>	<u>\$</u>	<u>3,014.00</u>



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 7751 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER		\$ 2,278.00	\$ 1,822.40	
2 FRONT BUMPER FIXING PARTS		\$ 256.00		
3 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 225.00		
4 FRONT BUMPER GRILLE - LOWER CENTRE		\$ 134.00		
5 FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE		\$ 192.00		
6 FRONT BUMPER SUPPORT ELEMENT - UPPER		\$ 59.00		
7 RADIATOR GRILLE		\$ 1,077.00		
8 FRONT BUMPER VENT GRILLE - RH		\$ 134.00		
9 FRONT WHEEL SPOILER - RH		\$ 51.00		
10 FRONT BUMPER GUIDE SECTION - RH		\$ 36.00		
11 FRONT FENDER - RH		\$ 979.00	\$ 782.80	
12 FRONT FENDER ATTACHMENT PARTS		\$ 57.00		
13 FRONT FENDER BRACKET - RH		\$ 52.00		
14 DEFORMATION ELEMENT BRACKET-RH REAR		\$ 49.00		
15 FRONT FENDER BRACE - RH LOWER		\$ 117.00	\$ 93.60	
16 WHEEL HOUSING LINER		\$ 237.00		
17 WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 44.00		
18 STONE CHIP GUARD		\$ 72.00	\$ 57.36	
19 ADHESIVE TAPE		\$ 54.00		
20 HEADLIGHT MOUNTING - RH		\$ 117.00	\$ 93.60	
SUB TOTAL SPARE PARTS	:	\$ 6,220.00	\$ 2,849.76	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKK 7751 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
	<i>c/f</i>		\$	2,849.76
21 HEADLAMP BRACKET - RH		\$ 105.00		
22 HEADLIGHT - RH		\$ 2,316.00	\$	1,852.80
23 GAS DISCHARGE LAMP		\$ 408.00		
24 DAY DRIVING LIGHTS POWER MODULE		\$ 538.00		
25 GAS DISCHARGE LAMP CONTROL UNIT		\$ 1,084.00		
26 RETAINING PLATE - RH		\$ 24.00		
27 HEADLIGHT HOSE - RH		\$ 36.00		
28 HALOGEN FOG LAMP - RH		\$ 259.00		
29 LIFT CYLINDER - RH		\$ 208.00		
30 FRONT NO PLATE	S/N	\$ 60.00		
31 SUNDRIES		\$ 300.00	\$	10.24
TOTAL SPARE PARTS	:	\$ 11,558.00	\$	4,712.80
TOTAL LABOUR CHARGES	:	\$ 6,114.00	\$	3,014.00
GRAND TOTAL	:	\$ 17,672.00	\$	7,726.80

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-03/11/20