

# SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TP MS16.  
Xiao Chen.

G771015219.

22 September 2020

## QUOTATION FOR ACCIDENT REPAIR OF SLB4026Y HONDA SHUTTLE

### THIRD PARTY INSURER: MSIG INSURANCE

S/No.	Parts List	Qty	Amount (\$)
1.	Rear tailgate <i>Disturbed</i>	1	\$ 1293.00 ✓ <i>1193.</i>
2.	Rear tailgate windscreen moulding <i>new</i>	1	\$ 175.00 ✓
3.	Rear tailgate "Logo" emblem <i>new</i>	1	\$ 76.00 ✓
4.	Rear tailgate "Shuttle" emblem <i>new</i>	1	\$ 78.00 ✓
5.	Rear tailgate "Hybrid" emblem <i>new</i>	1	\$ 85.80 ✓
6.	Rear tailgate no plate lamp L/R <i>new</i>	2	\$ 104.80 + <i>52.40</i>
7.	Rear tailgate no plate lamp garnish <i>new</i>	1	\$ 243.00 +
8.	Rear tailgate no plate top chrome <i>new</i>	1	\$ 480.00 +
9.	Rear tailgate hinge L/R <i>new</i>	2	\$ 133.20 + <i>66.20</i>
10.	Rear tailgate damper L/R <i>new</i>	2	\$ 330.00 + <i>165</i>
11.	Rear tailgate stopper RH	1	\$ 25.00 +
12.	Rear tailgate weather strip <i>new</i>	1	\$ 185.60 ✓
13.	Rear tailgate mechanism lock <i>new</i>	1	\$ 397.90 ✓ <i>187.50.</i>
14.	Rear tailgate lock striker <i>new</i>	1	\$ 39.00 +
15.	Rear tailgate inner trim <i>new</i>	1	\$ 435.80 ✓
16.	Rear tailgate inner trim handle <i>new</i>	1	\$ 56.10 +
17.	Rear taillamp RH <i>new</i>	1	\$ 520.50 ✓
18.	Rear taillamp panel (outer) <i>new</i>	1	\$ 255.00 +
19.	Rear bumper <i>Disturbed</i>	1	\$ 1080.60 ✓
20.	Rear bumper side reflector garnish RH <i>new</i>	1	\$ 109.80 ✓
21.	Rear bumper side reflector RH <i>new</i>	1	\$ 86.40 ✓
22.	Rear bumper side retainer L/R <i>new</i>	2	\$ 90.80 ✓ <i>45.40</i>
23.	Rear bumper towing cover <i>new</i>	1	\$ 48.00 ✓
24.	Rear end panel <i>Disturbed</i>	1	\$ 695.00 ✓ <i>560.80.</i>
25.	Rear end panel garnish <i>new</i>	1	\$ 205.80 ✓
26.	Rear spare tyre panel top board <i>new</i>	1	\$ 305.80 ✓
27.	Rear spare tyre panel top tray <i>new</i>	1	\$ 266.40 ✓
28.	Rear fender inner trim board RH <i>new</i>	1	\$ 849.20 ✓ <i>489.60.</i>
Subtotal before discount			\$ 8651.50
Discount 20%			\$ 1730.30
<b>Subtotal 1</b>			\$ 6921.20

S/NETT	Parts List	Qty	Amount (\$)
1.	Rear tailgate windscreen sealant <i>new</i>	1	\$ 60 ✓
2.	Rear tailgate reverse camera <i>new</i>	1	\$ 400 +
3.	Rear no plate <i>new</i>	1	\$ 30 +
4.	Rear no plate garnish <i>new</i>	1	\$ 50 +
5.	Rear bumper clip <i>new</i>	1	\$ 30 ✓
6.	Rear bumper reverse sensor <i>new</i>	1	\$ 350 ✓ <i>200.</i>
7.	Rear end panel sealant <i>new</i>	1	\$ 50 ✓
8.	Rear end panel garnish clip <i>new</i>	1	\$ 30 ✓
9.	Rear fender inner trim board clip <i>new</i>	1	\$ 30 +
<b>S/Nett Total</b>			\$ 1030

6181.20  
4944.96

370

# SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 68163103

Email : [Sinyusin@hotmail.com](mailto:Sinyusin@hotmail.com)

22 September 2020

**QUOTATION FOR ACCIDENT REPAIR OF SLB4026Y HONDA SHUTTLE**  
**THIRD PARTY INSURER: MSIG INSURANCE**

**Labour**

To check wiring and rectify electrical faults where necessary		\$ 60 <del>30</del>
To transfer tailgate mechanism and wiring assy		\$ 60 ✓
To remove, refix rear tailgate windscreen		\$ 150 <del>120</del>
To remove and replace and reinstall rear reverse sensor	2030	\$ 120 <del>50</del>
To remove & refix reverse camera assy		\$ 100 <del>50</del>
To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs		\$ 160 <del>60</del>
To rustproof affected areas		\$ 100 <del>60</del>
To straighten, repair, realign on front affected area and replace damaged parts		\$ 1000 <del>800</del>
To spray painting on affected area		\$ 1000 <del>800</del>
	Total Labour Cost	\$ 2750

Total Cost Of Repairs(Total cost of parts + Total labour cost) **\$ 10,701.20**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Adnan Lj  
h/s 23/09/20.  
06 Days

total: 7344.96.  
h/s: 5850.