




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS/LPC20010189/Gsd3e2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 21-10-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 855U	Veh. Inspected	SKC 323Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/20/20/VC00/023695	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	23/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 730LI	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA7E02040G245272	Colour	WHITE	
Odometer	153056	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	PIRELLI	6 mm	
L/H Front Tyre	245/50 R18	PIRELLI	6 mm	
R/H Rear Tyre	245/50 R18	PIRELLI	6 mm	
L/H Rear Tyre	245/50 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2020	Inspection Date	23/09/2020	
Survey held at	160 SIN MING DRIVE# 06-20			
Repairer	R C AUTO			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		