

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI20010190/T1vf3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 30-11-2020 Code: FCI2		
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 7293P	Veh. Inspected	NCA 8444	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D20003614MFSH	Excess (\$)	0.00	
	Assign From	MERINA CHIA SAN SAN	Assign Date	23/09/2020	
2.	2. Vehicle Particulars & Condition				
	Make & Model	NITRO NE125	c.c	124	
	Engine No.	HIDDEN	Year of Reg.	2004	
	Chassis No.	NT3XCJVD040115094	Colour	BLUE	
	Odometer	58058	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	80/90 R18	GOLDEN BOY	5 mm	
	L/H Front Tyre	00/00 D47	OOLDEN BOY	mm	
	R/H Rear Tyre	90/80 R17	GOLDEN BOY	5 mm	
	L/H Rear Tyre	<u> </u>	<u> </u>	mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION.				
_	DAMAGES SEE DETAILS.				
5.			Information	00/00/0000	
	Accident Date	04/09/2020	Inspection Date	23/09/2020	
	Survey held at KARZ WORKS PTE LTD 53 UBI AVE 1 #02-24 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934				
5a.	Remarks				
Ja.	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	3 Working Days		