

ASS. REC. BY:

Taufik

REF:

033/FC/20010190/71.883

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: _____

91500

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Damen

Veh No: _____

NCA8444

Yr Regn: _____

2004

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Nitrone 125

c.c

125

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

8058

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

NT3XCJVD040115094

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

80/90R14

R: _____

90/80R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Golden Boy

Front

Rear

R/Bal. _____

5 mm

R/Bal. _____

5 mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.I. _____

23/11/2004

Survey held at

Taman Gorge

Des. of Damages ☒ Fnt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Inform w/s upon limit \$800

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2) 26/11/20-Typist

Rep. Format: TP

Lump Sum / L.B. / P. LS \$800

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

KARZ WORKS PTE LTD

53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK

SINGAPORE 408934

(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

FIRST CAPITAL

REPAIR PERFORMA INVOICE

Vehicle number NCA8444
Make / Model NITRO SR125
Chassis number
Accident date 4/9/20
Reference KK2009-22

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1 SET	WING MIRROR	120 250.00 ant ✓
1 SET	FRONT FORK	Rp 700.00
1	SIGNAL LAMP LH	90.00 ant ✓
1	FRONT FENDER	180.00 bt ✓
1	FOOTREST	110.00 bt ✓
1	STAND	85.00 Rp
1	HANDLE BAR	200 350.00 bt ✓
1 SET	BALANCER	60 120.00 ant ✓
		1885.00 760
		Less 10%
		188.50
		Subtotal
		1696.50 684
		Balance C/F
		1696.50
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	GEAR SHIT SHAFT OIL SEAL	684
2	FORK OIL SEAL	430
1 BOT	FORK OIL	320
1	WINDSHIELD (AFTER MARKET)	1434
1	FRONT REINFORCEMENT BAR	1150
		Repair limit 4800
		Subtotal
		854.00 430
		Balance C/F
		2550.50
LABOUR AND MISCELLANEOUS CHARGES		
1	REPLACE , REALIGN AND ADJUST ABOVE DAMEGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM	350.00 200
2	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING	500.00 Xnn
3	TO REMOVE/REFIT, REPLACE FRONT FORK TUDES	300.00 120
4	SPRAY PAINTING & REPASTE STICKER	300.00 Xnn.
		Subtotal
		1450.00 320
		Grand total
		4000.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10%

Subtotal

Balance C/F

PARTS REPLACEMENT - SPECIAL NETT ITEMS

1 SET	GEAR SHIT SHAFT OIL SEAL	684	24.00 Xnn
2	FORK OIL SEAL	430	120.00 60.
1 BOT	FORK OIL	320	60.00 40.
1	WINDSHIELD (AFTER MARKET)	1434	150 250.00 cna ✓
1	FRONT REINFORCEMENT BAR	1150	180 400.00 bt ✓
		Repair limit 4800	Subtotal
			854.00 430
			Balance C/F
			2550.50

LABOUR AND MISCELLANEOUS CHARGES

1	REPLACE , REALIGN AND ADJUST ABOVE DAMEGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM	350.00 200
2	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING	500.00 Xnn
3	TO REMOVE/REFIT, REPLACE FRONT FORK TUDES	300.00 120
4	SPRAY PAINTING & REPASTE STICKER	300.00 Xnn.
		Subtotal
		1450.00 320
		Grand total
		4000.50

Tanphn 97495749 23/9/2005 30pm
Wp. Lanysona Repairing after repair!

Tanphn @ 11am to 1pm - 03 days