

KARZ WORKS PTE LTD

53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK

SINGAPORE 408934

(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

FIRST CAPITAL

REPAIR PERFORMA INVOICE

Vehicle number	NCA8444
Make / Model	NITRO SR125
Chassis number	
Accident date	4/9/20
Reference	KK2009-22

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1 SET	WING MIRROR	120 250.00 ant ✓
1 SET	FRONT FORK	Rp 700.00
1	SIGNAL LAMP LH	90.00 ant ✓
1	FRONT FENDER	180.00 bt ✓
1	FOOTREST	110.00 bt ✓
1	STAND	85.00 Rp
1	HANDLE BAR	200 350.00 bt ✓
1 SET	BALANCER	60 120.00 ant ✓
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____		1885.00 760
		Less 10% 188.50
		Subtotal 1696.50 684
		Balance C/F 1696.50
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	GEAR SHIT SHAFT OIL SEAL	684 24.00 Xnn
2	FORK OIL SEAL NEC	430 120.00 60.
1 BOT	FORK OIL NEC	320 60.00 40.
1	WINDSHIELD (AFTER MARKET)	150 250.00 cna ✓
1	FRONT REINFORCEMENT BAR	180 400.00 bt ✓
1434 1/58 1150 Repair limit 9800		Subtotal 854.00 430
		Balance C/F 2550.50
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	REPLACE , REALIGN AND ADJUST ABOVE DAMGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM	350.00 200
2	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING	500.00 Xnn
3	TO REMOVE/REFIT, REPLACE FRONT FORK TUDES	300.00 120
4	SPRAY PAINTING & REPASTE STICKER	300.00 Xnn.
Tan Jiah 97495749 23/9/20 0530pm Wp' kumpson Reentry after repair! Tan Jiah e 1karto.com - 03 days		Subtotal 1450.00 320
		Grand total 4000.50