




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC20008016/Atf3s2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 07-10-2020	
			Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YP 4951Z	Veh. Inspected	GBJ 4890U	
Policy No.	Z20VC05004878	Coverage (\$)	0.00	
Claim No.	20/20/20/VC05/023507	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	23/09/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTFAT35Y10K213076	Colour	WHITE	
Odometer	45079	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	155 R12C	BRIDGESTONE	6 mm	
L/H Rear Tyre	155 R12C	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/07/2020	Inspection Date	04/08/2020	
Survey held at	NO 8 KAKI BUKIT AVE 4 #03-46 PREMIER			
Repairer	GARAGE 13 PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>10 Working Days</b>		