



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007809
INV Date 19/11/2020
Reference CC4/FCI20010192/Eda3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLZ 1301X
Insured Veh. SH 7749K
Claim No. D20003843MFSH
Policy No. D-20094922MFSH
Accident Date 21/09/2020
Inspection Date 28/09/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20010192/Eda3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-11-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7749K	Veh. Inspected	SLZ 1301X
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20003843MFSH	Excess (\$)	0.00
Assign From	VIC	Assign Date	23/09/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 216I	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBA2D920905K81200	Colour	GREY
Odometer	34655	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R16	TOYO	5 mm
L/H Front Tyre	195/65 R16	TOYO	5 mm
R/H Rear Tyre	195/65 R16	TOYO	5 mm
L/H Rear Tyre	195/65 R16	TOYO	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/09/2020	Inspection Date	28/09/2020
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 1301X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
1	REAR BUMPER CARRIER (SN)	BENT	460.40	460.40
1	SUPPORT (SN)	BROKEN	45.55	45.55
1	RR BUMPER LH INNER SIDE GUIDE (SN)	NOT NECESSARY	61.35	-
1	RR BUMPER RH INNER SIDE GUIDE (SN)	NOT NECESSARY	61.35	-
1	REAR BUMPER TRIM STRIP (CHROM) (SN)	BROKEN	110.55	110.55
1	LEFT PROTECT (SN)	NOT NECESSARY	11.20	-
1	RIGHT PROTEC (SN)	NOT NECESSARY	11.20	-
1	REAR BUMPER PANEL PRIMED (LINES PDC) (SN)	DENTED	1,045.45	1,045.45
1	SET MOUNTS PDC SENSOR REAR (SN)	NOT NECESSARY	60.70	-
1	REAR BUMPER HEAT INSULATION (SN)	NOT NECESSARY	63.50	-
4	DECOUPLING RING PDC TORQUE CONVERTER (SN)	NECESSARY	20.40	20.40
4	ULTRASONIC SENSOR ATLANTIKGRAU (WC09) (SN)	NOT NECESSARY	1,527.60	-
			3,559.25	1,762.35
LABOUR				
TO REPLACE REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC.			1,275.00	850.00
TO SPRAY REAR BUMPER .			1,038.00	934.00
TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION .			177.00	150.00
			2,490.00	1,934.00
GRAND TOTAL			6,049.25	3,696.35
RECOMMENDED COST OF REPAIRS				3,696.35

Report Ref No. CC4/FCI20010192/Eda3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 1301X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 1301X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

