

28/9/2020
 Suny & Repin



Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 67449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

22 SEP 2020

ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 56065
 Date Estimated : 22/09/2020
 Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -
 Philip Chiang
 255 Bishan Street 22
 #11-462
 Singapore 570255

- ACCOUNT - 303
 MS First Capital Insurance Limited
 6 Raffles Quay
 #21-00
 Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ1301X	WBA2D920905K81200	24/04/2018	216i G TOURER	0

DESCRIPTION	VALUE
To replace rear bumper include remove attachment etc	850 1,275.00
To spray rear bumper	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	157 177.00
Sundries	? 80.00
Total Labour 1:	2,570.00

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CARRIER	1	460.40	460.40
SUPPORT	1	45.55	45.55
RR BUMPER LH INNER SIDE GUIDE	1	61.35	61.35
RR BUMPER RH INNER SIDE GUIDE	1	61.35	61.35
REAR BUMPER TRIM STRIP (CHROM)	1	110.55	110.55
LEFT PROTECT	1	11.20	11.20
RIGHT PROTEC	1	11.20	11.20
REAR BUMPER PANEL PRIMED (LINES PDC	1	1,045.45	1,045.45
SET MOUNTS PDC SENSOR REAR	1	60.70	60.70
REAR BUMPER HEAT INSULATION	1	63.50	63.50
DECOUPLING RING PDC TORQUE CONVERTER	4	5.10	20.40
ULTRASONIC SENSOR ATLANTIKGRAU(WC09	4	381.90	1,527.60
Total Parts :			3,479.25

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559N GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 5

Estimate No. : b1 56065
Date Estimated : 22/09/2020
Prepared By : Chua Kee Sin

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ1301X	WBA2D920905K81200	24/04/2018	2161 G TOURER	0

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 28/9/20, 10:30am Excess S\$ _____

Surveyor's Name Steve (LKK) Sign _____

Surveyor's Tel 8322 8813 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail ML PHL

No. of Working Days Recommend 3 days

*PIP
By Bel sy*



Labour 1	:	2,570.00
Parts	:	3,479.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	423.45
Grand Total	:	<u>6,472.70</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **