

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20010196/QPS3AQ2

Date: 13/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMS8036R	Insured Vehicle No :	SHC1193J
Date of Loss: 20/09/2020	Nature of Claim: TP	Claim No: MCT20090308

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS8036R		
Make & Model:	TOYOTA SIENTA 7-SEATER, 1.5 G CVT (A)	Engine No:	1NZR827167
Reg. Date:	16/03/2020 (Man. Year: 2019)	Chassis No:	NHP1707189643
Colour:	Blue	Odometer:	37949 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,221.00	5,344.00	4,877.00	47.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	801.57	626.07	175.50	21.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,022.57	5,970.07	5,052.50	45.84
Approved Total (Overridden) (S\$)		4,750.00		
(S\$)	11,022.57	4,750.00	6,272.57	56.91
+ GST 7.00/7.00% (S\$)	771.58	332.50	439.08	56.91
Nett Amount (S\$)	11,794.15	5,082.50	6,711.65	56.91
+ Loss of Use (5.0 x S\$40.00/day) (S\$)		200.00		
+ Car Rental (5.0 x S\$55.00/day) (S\$)		275.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,564.95		
Global Sum Settlement (S\$)		5,550.00		

INSPECTION

Date of Assignment:	23/09/2020	
Date Inspected:	23/09/2020 Inspected At:	Forza Autohaus Pte Ltd (HQ) No.39 Woodlands Close, #01-34/35, Mega@Woodlands Singapore 737856
Estimated Period of Repair:	3.0 days	

Adjuster: OI SUN PIN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Oct 2020)
Parts: M1-MPV	TOYOTA SIENTA 7-SEATER 1.5 G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS8036R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BUMPER INNER SPONGE BUMPER	Crumpled	112.00 F	*112.00 F	
2	1		*FRONT BUMPER	Crumpled	592.00 F	*592.00 F	
3	1		*FRT BUMPER REINF	Bent	304.00 F	*304.00 F	
4	1		*LEFT HEADLAMP ASSY	Serviceable	2,928.00 F	*- F	
5	1		*R/F LOWER BUMPER LID	Scratched	208.00 F	*208.00 F	
6	1		*R/F SHOCK ABSORBER	Serviceable	765.00 F	*- F	
7	1		*R/F STEERING KNUCKLE	Serviceable	528.00 F	*- F	
8	1		*R/F WHEEL COVER	Scratched	250.00 F	*250.00 F	
9	1		*R/F WHEELHOUSE COVER	Cut	208.00 F	*208.00 F	
10	1		*R/F WING	Crumpled	480.00 F	*480.00 F	
11	1		*R/LWR AXLE STEERING	Serviceable	656.00 F	*- F	
12	1		*R/UPPER RADIATOR BRKT	Cut	96.00 F	*96.00 F	
13	1		*RIGHT HEADLAMP ASSY	Crumpled	2,928.00 F	*2,928.00 F	
14	1		*SET FENDER CLIP	Necessary	30.00 FS	*30.00 FS	
15	1		*R/F WING INSULATOR	Necessary	136.00 FS	*136.00 FS	
					Total Parts (S\$)	10,221.00	5,344.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	69.0 WU X 45.00 SGD/H	New	310.50	135.00
2	LABOUR COST 55.0 WU X 70.00 SGD/H	New	385.00	385.00
3	MATERIAL COST	New	106.07	106.07
			Gross Labour Cost (\$\$)	626.07

Report was unsubmitted during this print-out.

< END OF ESTIMATES >