

ASS. REC. BY:

REF:

LPC / 20010197/Kba3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Hui Yang

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL7 4501R Yr Regn: 05.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda ^A Verel c.c. 1496

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 155473 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: B43 1288807

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Blm or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

A. Davanti

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 21/9/20

D.O.I. 23/9/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

& M

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/10 11 Am @ 99001 Center

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. \$

Fuel

Others

TOTAL

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) _____

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

1on pac
(LKK)
23/09/20

21/09/2020

Owner: SKYWAY MOTOR PTE LTD

Not Authorised
61 Simp @ 99000
Resurvey After Paint
8 days

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLZ4501R

1pc	rear tailgate	R	\$ 1,100.90	✓
2pcs	rear tailgate hinge @\$53.60	R	\$ 107.20	X
1pc	rear tailgate "HONDA" logo	M	\$ 27.00	—
1pc	rear tailgate "VEZEL" emble	M	\$ 55.10	—
1pc	rear tailgate "HYBRID" emblem	M	\$ 68.50	—
1set	rear tailgate windscreen moulding	M	\$ 120.00	—
1pc	rear tailgate outer garnish	mycm	\$ 285.50	✓
2pcs	rear tailgate RH refector	CM	\$ 350.80	—
1pc	rear tailgate inner lock	RL	\$ 198.40	—
1pc	rear tailgate inner rubber	Dis/RL	\$ 135.20	50% in
1pc	rear tailgate inner garnish	mycm	\$ 320.50	✓
1pc	rear tailgate inner handle garnish	SL	\$ 20.70	X
1pc	rear RH taillamp	CR	\$ 460.60	—
1pc	rear bumper 762.70	Bu	\$ 986.30	—
1pc	rear bumper RH side bumper	Bu/RL	\$ 255.20	✓
2pcs	rear bumper side retainer @\$24.80	cls/RL	\$ 49.60	—
1pc	rear end panel 415.60	R	\$ 580.90	—
1pc	rear end panel inner garnish	CM	\$ 109.90	—
1pc	rear end panel outer sensor	SL	\$ 195.25	X
2pcs	rear fender inner tirm @\$521.90	cls cm	\$ 1,043.80	✓
1pc	rear fender RH protector	RL	\$ 198.50	—
1pc	rear floor panel tirm board	BuK	\$ 450.20	—
1pc	rear floor panel inner garnish	mycm	\$ 285.50	—
2pcs	front headlamp @\$1759.40	mycm	\$ 3,518.80	—
2pcs	front headlamp lower bracket @\$35.00	cls cm	\$ 70.00	✓
2pcs	front headlamp top bracket @\$28.85	SL	\$ 57.70	X
1pc	front centre grille base 421.00	CM	\$ 542.20	—
1pc	front centrtre grille chrome	CM	\$ 108.00	—
1pc	front centre grille outer garnish	CM	\$ 385.00	—
1pc	front centre grille "HONDA" logo	M	\$ 58.85	—
1pc	front centre grille bracket	CM Ex	\$ 65.20	✓
1pc	front bumper 825.	Bu	\$ 927.50	—
2pcs	front bumper side retainer @\$21.70	cls Dis	\$ 43.40	✓
1pc	front bumper grille 165.00	Dis/CM	\$ 260.00	✓
1pc	front bumper lower spoiler	SL	\$ 351.00	X
20pcs	front bumper clip @\$5.00	M	\$ 100.00	✓ 50.00

balance c/f

\$ 13,893.20



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

21/09/2020

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLZ4501R

	balance b/f		\$ 13,893.20	
1pc	front bumper reinforcement	R	\$ 321.50	✓
2pcs	front bumper LH fog lamp garnish @\$95.58	Rd	\$ 191.16	R
1pc	front support panel	R	\$ 676.20	X
			\$ 15,082.06	
	less 20%		\$ 3,016.41	
			\$ 12,065.65	
1set	rear reverse sensor	Rd	s.nett \$ 280.00	2001A
1set	front / rear number plate & casing	Rd	s.nett \$ 100.00	901A
	remove & refix rear windscreen glass		\$ 120.00	✓
	wiring		\$ 120.00	401
	tuffkote		\$ 150.00	601
	sealant		\$ 120.00	301
	spray painting		\$ 1,800.00	11001
	labour charges		\$ 1,600.00	10001
	Total		\$ 16,355.65	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

