

Not Authored
Running B4psim

2 day

Vehicle Insured : SHD 3379 Y
Accident Date : 29-Aug-2020

No. : 31388
Date : 31-Aug-2020
PAGE : 1

Our Ref : 020401 (FIRST) / QUEK

LEE SIEW MEI CORINA (MS)
Singapore

ESTIMATED COST OF REPAIR FOR HYUNDAI AD AVANTE 1.6GLS(A) (2019) SMK1558P
=====

1 pc	front bumper	Bucl on	474.40	✓
1 pc	o/s front bumper side retainer	sn	15.00	X
1 pc	front bumper signallamp	sup	164.80	—
1 pc	front bumper lower side grille	sn	22.00	—
1 pc	front bumper lower side garnish	sn	25.00	X
1 pc	front bumper lower spoiler	sn	71.70	X
10 pcs	front bumper clips	@ S\$ 2.00	20.00	✓
1 pc	o/s headlamp assy		3,034.90	?
1 pc	o/s headlamp lower bracket		25.00	?
			3,852.80	
Less 20% :			-770.56	
			3,082.24	

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

300.00 22d

To focus headlamps. To check front
wiring and lighting operation.

30.00 2d

To putty and respray on affected
portions.

400.00 22d

Total : S\$ 3,812.24
=====

Singapore Dollars Three Thousand Eight Hundred
and Twelve and Cents Twenty Four Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

