

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: AIG Asia Pacific Insurance Pte Ltd

Policy No _____ Third Party _____

Date: 22.09.2020

Accident Date : 28.08.2020

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Vezel" Reg. No. SKW913P Claiming Against Your Insured Reg. No. SKJ3667Z			
1pc	Front Bumper / BR		762 963.00
10pcs	Front Bumper Clips / MC	3.8	38.00
1pc	Front Bumper Corner Retainer / BR		25.30
1pc	Front Fender Protector RH / BR		140.2 206.00
10pcs	Front Fender Protector Clips / MC	4.00	30 40.00
	Less 20%		995.5 1,272.30 796.4 254.46 <u>1,017.84</u>
	Labour Charge - Panel Beating, Repairing Of Front Fender and Parts Replacement		200 350.00
	To Respray Affected Areas		200 450.00
	Total :		<u>1,817.84</u>
			1196.4

2 Days.
 P/P
 before paint photos.
 Gino Q. are - 82880282
 23/9/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____