ASS. REC. BY: Marcus REF: CS/ C7/	20010201/4
	GNMENT
From: Date:	Veh No: GBB 49 45M Yr Regn: Yr Yr Yr Regn: Yr Yr Regn: Yr Yr Regn: Yr
ODYTP/WS/TP RES/OD RES/EVA/INV/MV	Truck/Trailer or (M/
To Inspect Vehicle No: GBB 4948M at Workshop m/s To Inspect Vehicle No: GBB 4948M	Make: Top to Dyng c.c 2982 Colour Wite A/C: Insured / Std / NI / NA
of	Sp.Reading 402250 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JTFAT35YOOK 200562 Gen. Cond: Good / Fair / Poor / Burnt
Claims No.	Steering: Ingreer / Jammed / Leaked / Burnt or
Sum Insured: Excess:	Brake: Interder / Jammed / Leaked / Burnt or
(Client's Record)	Modi: NiLLS/Rim / STD A/Rim or
Make of Veh:	Tura Size: F: 19 FRIT
(D. Eur Candition)	R: 155-R12
(Policy Condition) Remark: The veh had commenced its N/S O/S	(BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	ТОУО / УОКО or
Bal. or Market Value:	Front C Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6/6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6/6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 21/9/20 D.O.I. 23/9/20
Lum Sum: % 3 Val.: Yes or No	Survey held at
Lumoum	Des. of Damages : Frt / Bear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	A.
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction COE 19-5-2024 Be 3 3 3.7m MV \$1 8200 L7A \$10165 NV \$7835	
	The second secon
	Days Of Repair:
	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation: : Site Insp (\$)S + RS,SI
Add Fee	
Township.	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$: Weekend (\$)
	TOTAL

(08/11/13)

wef

SGCARMART.COM

Login Sign up

New Care

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Singapore Reckless Drivers Part VIII

COE Bidding - 1st Round of September 2020

Shift to new satellite base ERP system in...

toyota dyna

Price Range

➤ Depreciation ➤ > 10 year(! ➤ Vehicle Type

Advanced Search

Home » Used Cars » A&L Automobile Pte Ltd » Toyota Dyna 150 3.0M (COE till 07/2024)

Toyota Dyna 150 3.0M (COE till 07/2024)

Overview	Financial	Accessories	Similar	Research	Photos	Мар
Price	\$21,300		Lifespan		29-Sep-2024	
Depreciation (\$5,530 /yr		Reg Date		30-Sep-2004 (3yrs 10mths 8day	/s COE left)
Mileage	N.A.		Manufact	ured 🕜	2004	
Road Tax 🕥	N.A.		Transmis	sion	Manual	
Dereg Value	\$10,701 as	of today (change)	OMV ⊘		\$23,715	
COE 💮	\$13,880		ARF ()		\$1,186	
Engine Cap	2,986 cc		No. of Ov	ners 🕥	4	
Curb Weight 💮	1,500 kg					

Description

Type of Vehicle

Vehicle Is In Good And Well Maintained Working Condition, Prefect Commercial Vehicle To Sell. And Vehicle Comes With 1 Month Warranty. Please Contact Us For More Detail.

Category

COE Car

Status

Available

Resources



Car Valuation - Free

Truck

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 13-Sep-2020 | Last Updated on: 13-Sep-2020

Upfront Payment » more Financial info Transfer Fee 🗇 \$25 Down Payment ② \$2,130 (change) Maximum 90% Loan 1st Instalment \$489 Based on 4.5% Interest rate \$2,644 Total Upfront Payment Check with seller for exact figure (excluding insurance)

Products and Services

» View All









Shortlist

Compare

Report Error

More Actions

Seller Information

A&L Automobile Pte Ltd

1 vehicles for sale. 1 sold in past 3 mths

Q 11 Mandai Estate #05-09 Fldiy

Tel: 63627228 Search cars nearby Alan

90214919 🕲 Chervi 83827333 🕲 Guan 81984113 🕲 Richard 96212156

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	er en
Owner ID Type:	Company
Owner ID: Vehicle Details	818E
Vehicle No.:	GBB4945M
Vehicle to be Exported:	No
ntended Deregistration Date:	23 Sep 2020
ehicle Make:	TOYOTA
ehicle Model:	DYNA 150 MANUAL 3SEATER
rimary Colour:	White
lanufacturing Year:	2009
ngine No.:	1KD1924940
hassis No.:	JTFAT35Y00K200562
laximum Power Output:	
pen Market Value:	\$24,970.00
riginal Registration Date:	20 May 2009
rst Registration Date:	20 May 2009
ransfer Count:	2
octual ARF Paid: ntended PARF Rebate Details	\$1,249.00
ARF Eligibility:	No
ARF Eligibility Expiry Date:	-
ARF Rebate Amount: ntended COE Rebate Details	\$0.00
COE Expiry Date:	19 May 2024
OE Category:	C - Goods Vehicle & Bus
OE Period(Years):	5
QP Paid:	\$13,910.00
COE Rebate Amount:	\$10,165.00
Total Rebate Amount: Message	\$10,165.00
Please note that all future COE renewals for this vehicle vehicle.	e can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the

The information contained herein is correct as at 23 Sep 2020

Jin Auto Services Pte Ltd #01-410/412, 14 Defu Lane 10 539195

Insurer Reference: GBB4945M Repairer Reference: GBB4945M

Date calculated: 22/09/2020 5:05 PM

Full Report

Registration: GBB4945M Printed: 22/09/2020 5:15 PM

Summary Information

Claim

Location:

Printed by:

Singapore (SG)

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

JOUIS SEOW Currency: GBB4945M

SGD

21/09/20

Date of Incident: Hire Car Start: Hire Car End:

Estimated Repair Time: Actual Repair Days:

Claim Reference:

Vehicle Details

Vehicle

Manufacturer:

TOYOTA

Model: Sub Model: DYNA 150

Model Sheet Number:

70 1N 03 GBB4945M

Registration: VIN number:

JTFAT35Y00K200562

Odometer:

Model Specs

FROM 04/2009 3.0 LTR 80KW

AIR CONDITIONING TWO COAT METALLIC

Not Authorn 1 Non 24vess 3? 23/9/20 The, M. Atter re **REAR HEATER**

PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All **Underbody**

Labour

LKK Auto Consultants hence notify

the Repairer of the following:

· To resurvey before/after spray painting

· Parts prices are subject to confirmation

. Third party survey is on a "Without Prejudice" basis

· No illegal modification(s) is allowed

Signature:

Date:

· To display damaged part(s) during resurvey

· Supplementary items) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Time Base 10 WU/h

Price = 42.00 SGD/h

Code	Description	WU	Price SGD
NO NUMBER	RENEW FRONT PANEL	60.0	252.00
520011)	R + R FRONT BUMPER	4.0	16.80
520011)	RENEW FRONT BUMPER (REMOVED)	2.0	8.40
751011	R + R RADIATOR GRILLE	2.0	8.40
810051)	R + R LEFT HEADLAMP	1.0	4.20
010001)	(RADIATOR GRILLE REMOVED)		
810051)	R + R RIGHT HEADLAMP	1.0	4.20
,	(RADIATOR GRILLE REMOVED)		
810151A	ADJUST HEADLAMPS	3.0	12.60
NO NUMBER	R + R L/F LOWER CLOSING PANEL	1.0	4.20
NO NUMBER	R + R R/F LOWER CLOSING PANEL	1.0	4.20
NO NUMBER	RENEW FRONT NUMBER PLATE (REMOVED)	1.0	4.20
554011)	R + R WINDSCREEN	14.0	58.80
	INCLUDES: R + R SUN VISORS, UPPER FRONT		
	PANEL AND A-PILLAR TRIMS		
670051)	R + R LEFT FRONT DOOR	11 6.0	
670051)	R + R RIGHT FRONT DOOR	A4 6.0	
743201)	DETACH + REFIT HEADLINING	4.0	16.80
,	INCLUDES: R + R INSIDE MIRROR, PILLAR		
	TRIMS AND SEAT BELTS		a months and a second
NO NUMBER	R + R L/F LOWER DOOR SEAL	A 2.0 (
NO NUMBER	R + R R/F LOWER DOOR SEAL	11 2.0	
870031)	R + R HEATING CPL	12.0	50.40
870151	R + R BLOWER (HEATER REMOVED)	5.0	21.00
NO NUMBER	R + R EVAPORATOR	4.0	16.80
550451)	R + R INSTRUMENT PANEL	9.0	37.80
NO NUMBER	R + R INSTRUMENT PANEL CARRIER (REMOVED)	2.0	8.40
850161)	R + R WIPER MOTOR (WIPER UNIT REMOVED)	1.0	4.20
850171)	R + R WIPER LINKAGE	1.0	4.20
002019)	DRAIN + REFILL COOLANT	3.0	12.60
441101	R + R STEERING WHEEL	2.0	8.40
002889 ZAX	DRAIN AND REFILL AIR CONDITIONING	7.0	29.40
0418	UPPER FRONT PANEL REPAIR	1A 20.0* C	X 84.00
1410	WINDSCREEN SEAL CHECK		
	Lahaun Cash	Han Will	
	Labour Cost Panel / Mechanical Labour	Hrs WU 17.60 176.0	739.20
		17.60 176.0	
	Total of Labour		739.20
Paint	1 - 1 - A #		
Paint Work	SYSTEM AZT	Time Basis	10 WU/h
Code	Description - TWO COAT METALLIC	WU	Price SGD
	FRONT BUMPER NEW PART PAINTING	12.0	
en og gan myneret er er verklegen af 1854.	FRONT LOWER PANEL NEW PART PAINTING	19.0	
	UPPER FRONT PANEL NEW PART PAINTING	8.0	

Paint Material Per Part Code

NI KIK		

Description

Price SGD

PRINT DATE 22/09/2020

Paint Mater	rial Per Part				
Code	Description				Price SGD
0418 0410	UPPER FRONT PANEL NEW PART PAINTIN GRILLE NEW PART PAINT K1R	G			10.32 / 11.81 /
	Labour Cost - Paint Factor	42.00 SGD/h	Hrs	wu	Price SGD
	Time Paint			44.0	105.00
	Preparation Main Work Metal		2.50 0.50	25.0 5.0	105.00 21.00
	Preparation Comp. Work Plastic Total	10 WU/h	7.40	74.0	310.80
	Material Cost - Paint				Price SGD
	New Part Painting				60.18
	New Part Painting - Plastic K1R				11.81
	Material-constant Metal Preparation				28.60
	Material-constant Plastic				9.00

Spare Parts

Material-constant Plastic

Total

<u>- p</u>				prices as	s at 2015-06-01/01
Code		Description	Part Number	Part Source	Price SGD
Couc		Description.			40.00 400.00
0481	SCL	BADGE ~	75315 37011	Original /	400.00
0417	SIL	END MOULDING	53928 37011	Original wiper panel	block gamil 150.00
0281	745	FRONT BUMPER	52101 25912	Original	300.00
0414	10045	FRONT LOWER PANEL	55711 37051	Original	450.00
0257	suf	FRONT NUMBER PLATE	KNPL3	Original /s	30.00 سي
0410	cne	GRILLE /	53114 37010	Original —	210.00
4415	11	HEATER BLOWER CPL	NO STOCK	Original 乂	0.00
0561	11	LEFT HEADLAMP ASSY	81170 37171	Original X	350.00
0562	SIL		81130 37170	Original	350.00
0385	•	UPP RAD GRILLE SEAL	53119 37080B0	Original ?	20.00
1410		WINDSCREEN SEAL	56121 25040	Original ?	0.00
f: OEM Pa	rts	Savings			0.00
n: Non-OE	M Parts	Subtotal			2,260.00
u: Used pa	arts	Total			2,260.00

IPC Number plate \$30 Sneth Reputal X
IPC DYNA STICKER. NO.

109.59

Final Calculation

Tital Calculation	10 U	SGD	SGD
Parts Total Parts		2,260.00	2,260.00
Total 176.0 WU X 42.00 SGD/h		739.20	739.20
Total of Labour			
Paint Work Time Base 10 WU/h		310.80	
Labour Cost 74.0 WU X 42.00 SGD/h Material Cost		109.59	
Total Paint Including Material			420.39
Repair Cost Excludes GST			3,419.59
GST (+7.0%)	A STATE OF THE STA	11	239.37
Repair Cost Included GST			3,658.96

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.