LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Lionel Chua Date: 15 Oct 2020

Preliminary Advice

Vehicle No : GBB4945M Accident Date : 21/09/2020

Make : TOYOTA DYNA 150 Policy No. : DMCVSN3079781900

Assignment Date : 23/09/2020 Excess : \$\$500.00 Date of Inspection : 23/09/2020 Est. Duration of Repair : 5 days

Inspection At : Jin Auto Services Pte Ltd (Defu)

Blk 14 Defu Lane 10, #01-410/412

Singapore 539195

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :\$\$ 3,539.59 (inclusive supp \$120.00)

Revised Amount :S\$ 2,663.39 (inclusive supp)

Check Items (Estimated) :S\$ 0.00 Total :S\$ 2,663.39

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 18,000.00 COE / PARF Rebate :S\$ 10,165.00

Salvage Value :S\$

Margin for Repair :S\$ 7,835.00

Remarks

| (X) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. |
|-------|--|
| | Kindly let us have your authorisation. |

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ($\,$ X) Other comments : Kindly approve on supplementary amount \$ 120.00.