LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Lionel Chua Date: 24 Sep 2020

Preliminary Advice

Vehicle No : GBB4945M Accident Date : 21/09/2020

: DMCVSN3079781900 Make : TOYOTA DYNA 150 Policy No.

Assignment Date : 23/09/2020 **Excess** : S\$500.00 Date of Inspection : 23/09/2020 Est. Duration of Repair : 5 days

Inspection At : Jin Auto Services Pte Ltd (Defu)

Blk 14 Defu Lane 10, #01-410/412

Singapore 539195

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,419.59
Revised Amount	:S\$	2,551.39
Check Items (Estimated)	:S\$	20.00
Total	:S\$	2,571.39

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 18,000.00 COE / PARF Rebate 10,165.00 :S\$

Salvage Value :S\$

Margin for Repair 7,835.00 :S\$

Remarks

X	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage Kindly let us have your authorisation.	
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.	
)	Other comments :	