

Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VECHICLE NUM: MAKE & MODEL: MILEAGE: TYRE: SJD 8322 D
TOYOTA WISH

Subjust to insurand. CHASSIS NUM:		_ , , , ,
Ale I inter Rep.	<u>ن</u>	23/9/20
DESCRIPTION PARTS	уту	A 12 0/ ALL
1 BONNET Buc ~ 678:10	1	41396.00
BONNET LOGO (TOYOTA) New 66.50	1	125.00
BONNET INSULATOR NAY	1	\$ 593.00
4 BONNET HINGE (L+R) 11 ×	2	\$310.00
5 BONNET RUBBER STRIP NAX	2	\$372-00
BONNET STOPPER (L+R)	2	\$52.00
77 17 17 17 17 17 17 17 17 17 17 17 17 1	O 2	\$ 4264.W
THE LAW AND A CHART OF THE	2	\$ 540-00
HEADLAMP BRACKET (L+R)  HEADLAMP PANEL (L+R)	2	\$ 722.00
3	1	\$ 749.00
FRONT GRILLE CM 166.60	1	\$1911.00
FRONT BUMPER 7:15 645:10	1,786	\$310.00 0
2 FRONT BUMPER RETAINER (L+R) Sy 65: 50 x 27 131:00	0-5/15	- Marylin Anna Marian - Control
FRONT BUMPER GRILLE 73.7 148.20	1	\$ 480.00 L
FRONT BUMPER BRACKET (L+R)	2	11
FRONT BUMPER REINFORCEMENT BAR 14 295.35	1	\$ 873.00
FRONT BUMPER SPONGE	1	\$ 379.00
FRONT BUMPER FOG LAMP (L+R) 300 + MS CAL 1 PC \$415.00	2	\$ 830-00
FRONT BUMPER FOG LAMP GARNISH (L+R)	2	\$ 594.00
FRONT BUMPER FOG LAMP CHROME (L+R)	2	\$ 632 -00
FRONT FENDER (L+R)	2	\$1572.00
FRONT FENDER QUARTER GLASS MOULDING (L+R)	2	\$ 622-20
FRONT FENDER SIGNAL LAMP (L+R)	2	\$ 228.00
EPONT FENDER COWLING (I+R) Q1/70/4 / 188. 22 376.	40 2	\$ 576.00 -
FRONT FENDER TOP GARNISH (L+R)	2	\$ 252.00
EDONT SUPPORT PANEL 1.00.12	1	\$ 1013 - 00
EDONT SUPPORT PANEL TOP CARNISH 7 1/0.023	1	4497.00
AIDCON CONDENSOR	1	\$ 1253.00
THOU PRESCUE HOSE	1	\$ 497.00
LOW DDESCIDE HOSE	1	\$ 511.00
RADIATOR  LOW PRESSURE HOSE  A 1 ×  SVC ×	1	\$1497.00
		1.
RADIATOR SPARE TANK	1	\$ 150.00
SUCTION PIPE 17	1	\$ 403.00 -
DISCHARGE PIPE	1	\$450.00
RADIATOR FAN COWLING SUC X	1	\$ 812.00
RADIATOR FAN BLADE	1	\$176.00
RADIATOR FAN MOTOR	1	\$957-00
WIPER WASH TANK	1	\$ 240.00
WIPER WASH MOTOR 11 1	1	\$ 397.00
REAR WINDSCREEN MOULDING 128.70	1	\$ 391.00
TAILGATE 300/00/ 1248-10	1	\$ 1563-00

TAILGATE ENBLEM (DELUXE)  TAILGATE EMBLEM (VALVE MATIC)  TAILGATE EMBLEM (VALVE MATIC)  TAILGATE EMBLEM  TAILGATE EMBLEM  TAILGATE EMBLEM  TAILGATE LAMP (L+R)  TAILGATE HANDLE CHROME  TAILGATE HANDLE SWITCH  TAILGATE LOCK  TAILGATE LOCK  TAILGATE LOCK  TAILGATE LOCK  TAILGATE INNER BOARD  TAILGATE STOPPER (L+R)  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP		\$ (12.00 \$ (21.00 \$ (21.00 \$ (21.00 \$ (22.00 \$ 252.00 \$ 240.00 \$ 392.00 \$ (20.00)
TAILGATE EMBLEM (VALVE MATIC)  A TAILGATE EMBLEM  TAILGATE EMBLEM  TAILGATE LAMP (L+R)  TAILGATE HANDLE CHROME  TAILGATE CARPLATE LAMP (L+R)  TAILGATE HANDLE SWITCH  TAILGATE LOCK  TAILGATE LOCK  TAILGATE LOCK  TAILGATE LOCK CATCH  TAILGATE INNER BOARD  TAILGATE STOPPER (L+R)  TAILGATE WEATHERSTRIP	1 2 1 2 1 1 1 1	\$ 121.00 \$ 1452.00 \$ 1452.00 \$ 252.00 \$ 250.00 \$ 340.00 \$ 340.00
TAILGATE EMBLEM  TAILGATE LAMP (L+R)  TAILGATE HANDLE CHROME  TAILGATE CARPLATE LAMP (L+R)  TAILGATE HANDLE SWITCH  TAILGATE LOCK  TAILGATE LOCK  TAILGATE LOCK  TAILGATE LOCK CATCH  TAILGATE INNER BOARD  TAILGATE STOPPER (L+R)  TAILGATE WEATHERSTRIP	2 1 2 1 1 1	\$ 1452-00 \$ 427-00 \$ 250-00 \$ 340-00 \$ 340-00
TAILGATE HANDLE CHROME  TAILGATE CARPLATE LAMP (L+R)  TAILGATE HANDLE SWITCH  TAILGATE LOCK  TAILGATE LOCK  TAILGATE LOCK CATCH  TAILGATE INNER BOARD  TAILGATE STOPPER (L+R)  TAILGATE WEATHERSTRIP	2 1 2 1 1 1	\$ 1452-00 \$ 427-00 \$ 250-00 \$ 340-00 \$ 340-00
TAILGATE HANDLE CHROME  TAILGATE CARPLATE LAMP (L+R)  TAILGATE HANDLE SWITCH  TAILGATE LOCK  TAILGATE LOCK  TAILGATE LOCK CATCH  TAILGATE INNER BOARD  TAILGATE STOPPER (L+R)  TAILGATE WEATHERSTRIP	1 1 1 1	00.0764 4 250.00 4 240.00 4 240.00
TAILGATE CARPLATE LAMP (L+R)  TAILGATE HANDLE SWITCH  TAILGATE LOCK  TAILGATE LOCK  TAILGATE LOCK CATCH  TAILGATE INNER BOARD  TAILGATE STOPPER (L+R)  TAILGATE WEATHERSTRIP	1 1 1	4 252 -00 4 240-00 4 240-00
TAILGATE HANDLE SWITCH  TAILGATE LOCK  TAILGATE LOCK CATCH  TAILGATE INNER BOARD  TAILGATE STOPPER (L+R)  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP	1 1 1	\$ 392.00
TAILGATE LOCK  TAILGATE LOCK CATCH  TAILGATE INNER BOARD  TAILGATE STOPPER (L+R)  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP	1	\$ 392.00
TAILGATE LOCK CATCH  TAILGATE INNER BOARD  TAILGATE STOPPER (L+R)  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP	1	
TAILGATE INNER BOARD  TAILGATE STOPPER (L+R)  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP	1	1100
TAILGATE STOPPER (L+R)  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP  TAILGATE WEATHERSTRIP		4 693.00
TAILGATE WEATHERSTRIP 7~, 299.50		\$ 60.00
2/4.50	6.	Name of the last o
TAIL LAMP (L+R)	1	4379.00
TAIL LAMD DANEL (LAD)	2	\$1963.00
	1	4874.00
REAR BUMPER DI ( 492.35	1	\$1279.00
7 REAR BUMPER TOP RETAINER (L+R) 11 X	2	\$37.00
8 REAR BUMPER RETAINER (L+R) 65.50 x 27 131.00	2	1394.00
REAR BUMPER REINFORCEMENT BAR VSX	1	\$ 819.00
REAR BUMPER BRACKET (L+R) MS DPC 68.00 \$307.00	2	\$ 614.00
1 REAR BUMPER BEAM V S X	1	NIC
REAR BUMPER SPONGE $\sim$ S $\sim$	1	MIL
REAR BUMPER REFLECTOR (L+R) CM 68.10 x 22 137.00	2	\$ 494.00
	-7	-
5 REAR FENDER (L+R)	2	\$ 5776.00
REAR FENDER QUARTER WINDOW MOULDING (L+R)	2	\$ 612.00
REAR FENDER INNER TRIM UPPER (L+R)	2	41220.00
REAR FENDER INNER TRIM LOWER (L+R)	2	\$ 1694.00
REAR FENDER AIR VENT (L+R)	2	\$320-00
REAR FENDER COWLING (L+R)	2	\$512.00
REAR FENDER MUDFLAP (L+R)	2	\$ 490.00
END DANIEL 1 1/20 - 199.10	t	\$ 1021.00
END DANEL TOD CADNISH	1	4 612.00
DEAD SMADT LOCK ANTENNA	1	4 379.00
CDADEWHEEL DANEL 0 .1	1	41360-00
	1	4 675.00
EVHATIST DIDE	- 8	4918.00
1	1	100000000000000000000000000000000000000
EXHAUST GASKET	1	\$ 250.00
EXHAUST BRACKET (L+R)	2	4332.00
EXHAUST HEAT SHIELD	1	\$389.00
7-10824-50 SUBTOTAL		s -
\$   18.3 \tag{25%}		s -
PARTS TOTAL		s -
SPECIAL NETT	QTY	PRICE
BONNET INSULATOR CLIPS	10	S 100.00
FRONT BUMPER CLIPS W	10	S 100.00

4 FRONT CARPLATE FRAME	1	\$	120.00
5 FRONT FENDER COWLING CLIPS $ \sqrt{4} $	10	\$	100.00
6 FRONT FENDER QUARTER WINDOW SEALANT 11 X	1	s	120.00
7 RADIATOR COOLANT NAX	1	s	100.00
8 REAR WINDSCREEN SEALANT	1	S	120.00
9 TAILGATE INNER BOARD CLIPS ALL	10	s	100.00
10 TAIL LAMP CLIPS	4	S	80.00
11 REAR CARPLATE	1	\$	120.00
12 REAR CARPLATE FRAME	1	S	120.00
13 REAR BUMPER CLIPS	10	\$	100.00
14 REAR FENDER SEALANT 11 X	1	s	120.00
15 REAR FENDER QUARTER WINDOW SEALANT 17	1	\$	120.00
16 REAR FENDER INNER TRIM CLIPS $\wedge \wedge \wedge \times$	10	\$	100.00
17 REAR FENDER COWLING CLIPS 17 X	10	\$	100.00
18 REAR QUARTER PANEL SEALANT	1	\$	120.00
19 END PANEL SEALANT	1	\$	120.00
20 SPAREWHEEL PANEL SEALANT	1	\$	120.00
n Rear bumper Reverse Sensor Set (Refer to parts no. 64) \$ 250.00	-	1	450
SPECIAL NETT TOTAL		\$	1,440.00
LABOUR	QTY		PRICE
1 TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	1	S	6,300.00
2 TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$	4,200.00
3 TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$	600.00
4 TO RNR REAR WINDSCREEN	1	\$	400.00
5 TO RNR A/C CONDENSOR ASSY AND REFILL GAS	1	s	300.00
6 TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	1	\$	150.00
7 TO CHECK WIRING LAYOUT AND FOG LAMP FUNCTION	1	s	150.00
5 TO RNR REAR FENDER QUARTER WINDOW	1	\$	400.00
6 TO RNR UPHOSTERY, GARNISH AND ATTACHMENT PARTS	1	\$	1,200.00
7 TO RNR REVERSE SENSOR & CHECK FUNCTION.	1	s	150.00
8 TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	1	\$	450.00
9 TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION RESALT	1	\$	150.00
TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	1	\$	350.00
TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	1	.\$	800.00
1 TO DO WATER LEAK TEST.	1	\$	120.00
			3
1: \$4390 PS O TOTAL	L	\$	15,720.00
LKK Auto Consultants hence notify GRAND TOTAL COST	Г	s	17,160.00
the Repairer of the following:			0.1111
To display damaged part(s) during resurvey  To display damaged part(s) during resurvey  P = 8118.3			
Parts prices are subject to confirmation	1		D.
Third party survey is on a "Without Prejudice" basis  No illegal modification(s) is allowed  Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	PAGE 2 OF 2	B	
<ul> <li>No illegal modification(s) is allowed</li> </ul>			

Acknowledged by Repairer

Signature:

Date:

12998.37