

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
SOMPO INSURANCE SINGAPORE PL			Ref:	CS3/SMO20010212/	T1Utd3e2
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623				02-10-2020	
			Code:	SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKE 3545T	Veh. Inspected		FBQ 8701U
	Policy No.		Coverage (\$)		0.00
	Claim No.	CMTD2002644/THE	Excess (\$)		0.00
	Assign From	GRACE TEO	Assign	n Date	23/09/2020
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA AEROX GDR155A	c.c		155
	Engine No.	HIDDEN	Year o	of Reg.	2019
	Chassis No.	MH3SG4640KJ062576	Colou	r	BLACK
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modifi	cation	NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	100/80 R14	CORSA	4	6 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	120/70 R14	CORSA	4	6 mm
	L/H Rear Tyre				mm
4.	Description of Damages				
	THE VEHICLE SUS PORTION.	SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT			
5.	General Information				
	Accident Date	09/09/2020	Inspec	ct Date / Time	23/09/2020 (02:00 PM)
	Survey held at M 1 MOTORING				
	411 CHANGI ROAD SINGAPORE 419860				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b.	Estimate Days of Repair				

Report Ref No. CS3/SMO20010212/T1Utd3e2

Inspected By

Licensed Appraiser

CHUA KANG SENG

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

6 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.