

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# SGV3916P

Accident Date : 22/9/2020

Location : STILL RD (ECP) B4 MARINE PARADE ROAD EXIT

Model: TOYOTA COROLLA AXIO

27/8/2015

3P: SFK32D (AIG)

NZE1416020525

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>new</i>	65510 781.40	-	-
2	10 pcs	Rear bumper clips <i>new</i>	-	40.00	-
3	1 pc	Rear bumper o/s retainer <i>new</i>	31 81.35	-	-
4	2pcs	Rear bumper o/s & n/s screw <i>new</i>	-	10.00	-
5	1 pc	Rear bumper o/s stay <i>new</i>	86.30	-	-
6	1 pc	Rear boot cover <i>Buckled</i>	801 974.4	-	-
7	1pc	Rear boot cover 'AXIO' emblem <i>new</i>	61.7	-	-
8	1pc	Rear boot cover 'X' emblem <i>new</i>	59.5	-	-
9	1pc	Rear boot cover lock (Upper) <i>new</i>	185 291.6	-	-
10	1pc	Rear boot cover weatherstrip <i>new</i>	174.4	-	-
11	1pc	Rear boot cover emblem <i>new</i>	61.5	-	-
12	1 pc	Rear end panel <i>new</i>	581.90	-	-
13	1pc	Rear end panel inner trim <i>new</i>	253.50	-	-
14	1pc	Rear o/s tail-lamp <i>new</i>	984.40	-	-
15	1pc	Rear o/s tail-lamp seal <i>new</i>	60.00	-	-
16	1 pc	Rear o/s tail-lamp panel <i>new</i>	431.80	-	-
17	1 Set	Rear reverse sensor <i>new</i>	-	380.00	-
18	1 pc	Sound proof sticker <i>new</i>	-	200.00	-
		Sub-Total:	4,883.75	630.00	0.00
		After Less %:	25%	0%	10%
		2701.40	3,662.81	630.00	0.00

	Labour	
1	To remove and replace rear damage parts	1,000.00 <i>8w</i>
2	To spray painting	800.00 <i>600</i>
3	To remove and replace rear reverse sensor	50.00
4	To check wiring.	50.00 <i>30</i>
5	To re-seal anti-rust.	80.00 <i>60</i>
	Sub-Total:	1,980.00
	Total:	6,272.81
	After Less 20%:	5,018.25

Chan San Choon

Director

DipEng, AAE, MIM, SPM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Accredited Certification Body

bizSAFE

8778 1999

24 hr accident call

Mobil 1

