

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20010230/KGS3Q2**Date:** 14/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900089216
Claimant Vehicle No :	SKN3936B	Insured Vehicle No :	SMK6869J
Date of Loss:	20/09/2020	Nature of Claim:	TP
		Claim No:	9074427053SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN3936B		
Make & Model:	PORSCHE CAYENNE, 3.6 V6 E5 TIPTRONIC (A)	Engine No:	C02845
Reg. Date:	06/10/2011 (Man. Year: 2011)	Chassis No:	WP1ZZZ92ZCLA01806
Colour:	Metallic Black	Odometer:	154632 km
Engine Capacity:	3598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R18	Rear Tyre Size:	255/55 R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,215.50	10,689.50	3,526.00	24.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	1,400.00	550.00	28.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,165.50	12,089.50	4,076.00	25.21
+ GST 7.00/7.00% (S\$)	1,131.59	846.27	285.32	25.21
Nett Amount (S\$)	17,297.09	12,935.77	4,361.32	25.21
+ Car Rental (6.0 x S\$180.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		14,017.77		
Global Sum Settlement (S\$)		14,000.00		

INSPECTION

Date of Assignment:	23/09/2020		
Date Inspected:	25/09/2020	Inspected At:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S DOOR	Bent	4,700.00 FL	*3,450.00 FL
2	1		*FRONT O/S DOOR LOWER GARNISH	Dented / Warped	835.00 FL	*835.00 FL
3	1		*FRONT O/S DOOR RUBBER -INNER (50%)	Necessary	585.00 FS	*325.00 FS
4	1		*FRONT O/S DOOR RUBBER -OUTER (50%)	Necessary	553.50 FS	*307.50 FS
5	1		*REAR O/S DOOR	Bent	4,700.00 FL	*3,450.00 FL
6	1		*REAR O/S DOOR LOWER GARNISH	Dented	525.00 FL	*525.00 FL
7	1		*REAR O/S DOOR RUBBER -INNER (50%)	Necessary	495.00 FS	*275.00 FS
8	1		*REAR O/S DOOR RUBBER -OUTER (50%)	Necessary	553.50 FS	*307.50 FS
9	1		*REAR O/S DOOR RUBBER -FRONT	Cut	145.00 FL	*145.00 FL
10	1		*REAR O/S DOOR RUBBER -REAR	Cut	400.00 FL	*400.00 FL
11	1		*O/S SIDE SKIRT	Cut	725.00 FL	*725.00 FL
12	1		*REAR O/S WHEEL ARCH GARNISH	Cut	575.00 FL	*575.00 FL
13	1		*FRONT RH DOOR TOP WEATHER STRIP (50%)	Necessary	351.00 FS	*195.00 FS
14	1		*REAR RH DOOR WEATHER STRIP (50%)	Necessary	333.00 FS	*185.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,476.00	11,700.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,260.50	1,010.50
Total Parts (S\$)	14,215.50	10,689.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REWIRE TWO DOOR AIR BAG WIRING RESET AIR BAG SYSTEM	New	250.00	180.00
2	TO REPAIR REAR O/S SPORT RIM	New	200.00	120.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	800.00	600.00
4	TO REMOVE ,CUT -OUT DAMAGED PARTS, PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	700.00	500.00
Gross Labour Cost (\$\$)			1,950.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >