

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06243

Vehicle Insured : SMK 6869J
Accident Date : 20-Sep-2020

Date : 23-Sep-2020

Our Ref : 020122 (AIG) / CHAN

PAGE : 1

ANTONIO ONG KWEE KAY
56 FARRER ROAD
#02-01
Singapore 268844

ESTIMATED COST OF REPAIR FOR PORSCHE CAYENNE TIPTRONIC SKN3936B

1 pc	Front o/s door	4,700.00
1 pc	Front o/s door lower garnish	835.00
1 pc	Front o/s door rubber-inner	650.00
1 pc	Front o/s door rubber-outer	615.00
1 pc	Rear o/s door	4,700.00
1 pc	Rear o/s door lower garnish	525.00
1 pc	Rear o/s door rubber-inner	550.00
1 pc	Rear o/s door rubber- outer	615.00
1 pc	Rear o/s door rubber-front	145.00
1 pc	Rear o/s door rubber-rear	400.00
1 pc	O/s side skirt	725.00
1 pc	Rear o/s wheel arch garnish	575.00

15,035.00

Less 10% : 1,503.50

13,531.50

To rewire two door air bag wiring &
reset air bag system 250.00

To repair rear o/s sport rim 200.00

To putty and spray replaced parts 800.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts 700.00

Total : S\$15,481.50

=====

Singapore Dollars Fifteen Thousand Four Hundred
and Eighty One and Cents Fifty Only