



# ALLSWELL MOTOR TRADERS

25, Defu Lane 9, Singapore 539266

GST Reg No.: 53192889J

Tel No.: 6679 1146 / 91478545

Email: ben@allswellmotor.com.sg

account5@allswellmotor.com.sg

(3rd Party Claim Against MS FCI insured SUC 8800U )  
DOA 05.09.2020

## Repair Estimate

Vehicle No. : SGJ943T  
Make & Model : Honda Civic 1.8 LCA)

Submitted by : Ben  
COE Expiry : 28.06.2021

S/No	Part Description	Qty	Price	Unit Price	Disposition by
01	Rear bumper / RL	01	\$900.00	638	
02	RH reflector / RL	01	\$55.00	22.3	
03	REVERSE sensor X2 X	01	\$180.00		
04	Rear exhaust X	01	\$820.00		
05	TAN cover X	01	\$45.00		
				660.3	
				-20%: 528.24	
Special nett					
01	Cups & retainer studs @ \$20/pc / MS	01	\$20.00		
Labour Description					
01	Remac/assemble rear bumper	01	\$150.00	200	
02	Panel knocking on end panel	01	\$200.00		
03	Spray painting on rear bumper, polish & wash	01	\$300.00	200	
04	Anti-rust & waterproofing	01	\$120.00	X NV	
05	Sensor wiring	01	\$80.00	40	
				988.24	
				-20%: 800	

2 Days

ump sm repair  
After repair photos.

**KK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

**Note:** If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged according to the under supplement conveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Emo Qiang - 82880282  
28/9/2020.