



Address : 1, Kaki Bukit Avenue 6 #02-22/20 Autobay S(417883)
 Reg: 201828067M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair work
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
 Signature: *Khanhac*
 Date: *20.10.2017*

VEHICLE REPAIR ESTIMATE

Insurance Company: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Signature:

Date:

Address: NO 3, ANSON ROAD, #16-00, SPRINGLEAF TOWER S(079909)

Telephone: 63896111 Fax: 62221033 Email e-claims@gg.cntaiping.com

Make/ Model : OPEL ASTRA Date: 23.09.2020

Chassis No : W0LBE6EA9HG170602 Vehicle No: SMU3219C

Date/Time of Accide: 22.09.2020/1700 Date of Reg: 20.10.2017

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	NETT PRICE \$	FINAL PRICE \$
1	FRONT BONNET <i>Repw</i>	1	\$ 1,758.90	\$ + 1,758.90
2	FRONT BONNET LOCK <i>3M</i>	1	\$ 312.60	\$ + 312.60
3	FRONT BONNET STOPPER <i>3M</i>	2	\$ 40.00	\$ + 80.00
4	FRONT BUMPER <i>Dishled</i>	1	\$ 1,994.50	\$ ✓ 1,994.50
5	FRONT BUMPER TOW COVER <i>deltd</i>	1	\$ 128.70	\$ ✓ 128.70
6	FRONT BUMPER LOWER LIP RH <i>deltd</i>	1	\$ 185.90	\$ ✓ 185.90
7	FRONT BUMPER SIDE RETAINER RH-GUIDE <i>new</i>	1	\$ 136.90	\$ + 136.90
8	FRONT BUMPER SIDE RETAINER RH-UPP <i>could</i>	1	\$ 106.80	\$ ✓ 106.80
9	FRONT BUMPER BRACKET RH-UPP <i>new</i>	1	\$ 192.50	\$ + 192.50
10	FRONT BUMPER UNDER DUST COVER <i>new</i>	1	\$ 290.70	\$ + 290.70
11	FRONT BUMPER BRACKET TOP CENTRE <i>could</i>	1	\$ 198.60	\$ ✓ 198.60
12	FRONT BRACE BRACKET CENTRE <i>new</i>	1	\$ 229.70	\$ + 229.70
13	FRONT BRACE BRACKET RH <i>new</i>	1	\$ 118.90	\$ + 118.90
14	FRONT BUMPER SPONGE <i>could</i>	1	\$ 254.80	\$ ✓ 254.80
15	FRONT BUMPER REINFORCEMENT UPP METAL <i>bet</i>	1	\$ 798.60	\$ ✓ 798.60
16	FRONT REINFORCEMENT LOWER FIBRE <i>could</i>	1	\$ 374.20	\$ ✓ 374.20
17	FRONT BUMPER PARKING SENSORS <i>1 piece each</i>	4	\$ 272.60	\$ 272.60 1,090.40
18	FRONT BUMPER PARKING SENSOR SEAL <i>new</i>	1	\$ 48.00	\$ ✓ 48.00
19	FRONT PARKING SENSOR WIRE HARDNESS <i>new</i>	1	\$ 394.20	\$ + 394.20
20	FRONT GRILLE ASSY <i>could</i>	1	\$ 800.90	\$ ✓ 800.90
21	FRONT GRILLE LOGO <i>new</i>	1	\$ 160.20	\$ ✓ 160.20
22	FRONT LOWER CENTRE GRILLE <i>new</i>	1	\$ 202.90	\$ + 202.90
23	FRONT LOW GRILLE RH <i>new</i>	1	\$ 132.10	\$ + 132.10
24	HEADLAMP RH (ILUX) <i>could</i>	1	\$ 820.90	\$ ✓ 820.90
25	HEADLAMP BRACKET RH <i>could</i>	1	\$ 152.60	\$ ✓ 152.60
26	HEADLAMP LED CONTROL UNIT RH <i>new</i>	1	\$ 746.20	\$ + 746.20
27	FOGLAMP RH <i>new</i>	1	\$ 434.90	\$ + 434.90
28	FOGLAMP COVER RH <i>could</i>	1	\$ 120.80	\$ ✓ 120.80
29	FRONT FENDER RH <i>Deltd</i>	1	\$ 685.90	\$ ✓ 685.90
30	FRONT FENDER INNERSHIELD RH <i>3M</i>	1	\$ 138.70	\$ + 138.70
31	FRONT FENDER BRACKET RH <i>3M</i>	1	\$ 192.80	\$ + 192.80

32	FRONT FENDER SIGNAL LAMP RH <i>new</i>	1	\$ 146.90	\$ + 146.90
33	RADIATOR SUPPORT PANEL TOP GARNISH RH <i>new</i>	1	\$ 152.80	\$ + 152.80
34	RADIATOR SUPPORT PANEL TOP	1	\$ 385.90	\$ + 385.90
35	RADIATOR SUPPORT PANEL BOTTOM	1	\$ 485.20	\$ + 485.20
36	SUPPORT PANEL TOP GARNISH	1	\$ 198.60	\$ + 198.60
37	FRONT HEADLAMP PANEL RH <i>new</i>	1	\$ 185.90	\$ + 185.90
38	FRONT RADIATOR	1	\$ 1,424.80	\$ + 1,424.80
39	FRONT RADIATOR FAN ASSY	1	\$ 1,806.70	\$ + 1,806.70
40	FRONT RADIATOR TOP MOUNTING	1	\$ 18.90	\$ + 18.90
41	FRONT RADIATOR BRACKET LOWER RH <i>new</i>	1	\$ 162.80	\$ + 162.80
42	INTERCOOLER AIR GUIDE <i>new</i>	1	\$ 514.90	\$ + 514.90
43	AC CONDENSER	1	\$ 730.20	\$ + 730.20
44	AC CONDENSER TOP SEAL	1	\$ 112.50	\$ + 112.50
45	AC CONDENSER AIR GUIDE TOP CENTRE <i>new</i>	1	\$ 158.90	\$ + 158.90
46	AC CONDENSER AIR GUIDE RH	1	\$ 134.80	\$ + 134.80
47	AC AMBIENT SENSOR <i>new</i>	1	\$ 317.90	\$ + 317.90
48	WHEEL BEARING WITH HUB RH <i>new</i>	1	\$ 389.50	\$ + 389.50
49	KNUCKLE ARM RH <i>new</i>	1	\$ 385.20	\$ + 385.20
50	FRONT SHOCK ABSORBER RH <i>new</i>	1	\$ 398.50	\$ + 398.50
51	FRONT STABILIZER LINK RH <i>new</i>	1	\$ 194.50	\$ + 194.50
52	FRONT LOWER ARM RH <i>Best</i>	1	\$ 398.60	\$ + 398.60
53	FRONT RIM RH <i>new</i>	1	\$ 985.60	\$ + 985.60
Total Price Cost				\$ 22,973.40
				NETT DICOUNT 10% \$ 20,676.06

9008-10
8102-79

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT NUMBER PLATE WITH CASING <i>new</i>	1 SET	\$ 50.00	\$ + 50.00
2	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ + 30.00
3	FRONT FENDER INNESHIELD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ + 30.00
4	COOLANT <i>new</i>	1 SET	\$ 60.00	\$ + 60.00
Total Special Nett Items				\$ 170.00

30

Labour Works/ Panel Beating Related Works		
Job Scope	Quotation	
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 1,800.00	
<i>600</i>		
Spray Painting		
Job Scope	Quotation	
TO RESPRAY AFFECTED AREAS	\$ 1,800.00	
<i>600</i>		
Others Cost (Accident Repair Related Expenses)		
Job Scope	Quotation	
TO TUFFCOAT AFFECTED AREA	\$ 40 200.00	
TO CONDUCT WIRING CHECKS ON FRONT HEADLAMP	\$ 30 120.00	
TO REMOVE/ REPLACE / REFIT CONDENSER AND TOP UP GAS	\$ + 120.00	
TO REMOVE/ REPLACE FRONT SENSORS AND DISTANCE SETTLING	\$ + 150.00	
Total Others Cost	\$ 590.00	
GRAND TOTAL		\$ 27,333.40

To remove undercarriage
To perform wheel alignment

350 150
150 80

1500
total: 9632.79 / 05 Days
11/10/7-7/11