



Case Details

Case Reference Number : TAX/09/20/2054
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4845S

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-12685-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd
 Accident Date and Time : 22/09/2020 11:24 AM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation			Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)				Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair	✓ X R
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ / Nec
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	✓ X Svc
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	✓ X Svc
Total Spare Part Cost									3,738.72	Surveyor Total		120.00		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									2,990.98	Final Sur Total		96.00		

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	88.88	Replace	0	0	Not Give	X Svc
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	X Svc
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	X Svc
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Check	X Svc
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	X Svc
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	X Svc
One Time Key In	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.92	Replace	0	0	Not Give	X Svc
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Not Give	X Svc
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	X Svc
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Give	X Svc
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give	X Svc
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	X Svc
One Time Key In	Main			NAME PLATE (PRUIS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Give	X Svc
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	X Svc
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	X Svc

Total Spare Part Cost	3,738.72	Surveyor Total	120.00
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	2,990.98	Final Sur Total	96.00

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			STICKER DECAL 65558888	1	21.80	21.80	0.00	21.80	Replace	0	0	Not Give	X Svc
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Not Give	X Svc
Total Spare Part Cost									3,738.72	Surveyor Total		120.00		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									2,990.98	Final Sur Total		96.00		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	200	/
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	/
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY REAR PANEL	180.00	0	
4	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
Total:			918.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
2	Main	TO REPLACE SUNDRY PARTS	100.00	0	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/
4	Main	TO WASH AND VACUUM	60.00	0	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	/
Total:			740.88	316.88	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TOWING CHARGE	84.00	0	
Total:			740.88	316.88	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,990.98	96.00
Total Labour Cost	507.00	200.00
Total Spray Painting	918.00	200.00
Other	740.88	316.88
Overall Total	5,156.86	812.88
Lump Sum Repair Option	-	<input checked="" type="checkbox"/>
Lump Sum Total	5,150.00	800.00
Surveyor Approved Amount		800.00
No of Repair Days*	5	3 3 days.
Remarks	-	L/S, After paint photo
Surveyor Name		Sun Pin (LKK)
Signature:		

Save Clear

Survey Date 23/09/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: