

**Section A - Accident Details**

Registration Number	SHC4845S
Case Reference Number	TAX/09/20/2054
Registration Date	11/11/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SIN WAI MENG
Type of Accident	Head to Rear
Accident Date and Time	22/9/2020 7:24 PM
Accident Reported Date and Time	23/9/2020 8:47 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108246
Special Instruction to ARC if any	REAR RIGHT PORTION
Prepared Date and Time	23/9/2020 10:57 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

**Section B - Summary of Repair Estimates**

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$918.00	\$200.00
Total Spare Part Cost	\$2,990.98	\$96.00
Total Other Cost	\$740.88	\$376.88
<b>TOTAL COST</b>	<b>\$5,156.86</b>	<b>\$872.88</b>
<b>Lump Sum Total</b>	<b>\$5,150.00</b>	<b>\$850.00 (L/S)</b>
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / III
ARC / Surveyor Sign Off Date	23/09/2020 4:16 PM	23/09/2020 4:07 PM
Signature		
Remarks		L/S, After paint photo

**Section C - Quotation and Accident Invoice Details**

Quotation Number	QN-2010-0047	Invoice Number	
Quotation Date	06.10.2020	Invoice Date	
Invoice Amount		Prepared Date	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00 ✓
<b>Total Labour</b>	<b>\$507.00</b>	<b>\$200.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$918.00</b>	<b>\$200.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88 ✓
TOWING CHARGE	\$84.00	\$60.00 ✓
<b>Total Other Costs</b>	<b>\$740.88</b>	<b>\$376.88</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		89997-30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given X
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		90467-07211	BUMPER CLIPS	0.00	\$2.10	0.00	\$0.00	Replace	Not Given X
		52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair ✓
		81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given X
			STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given X
			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given X
		75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given X

SVC  
R  
SVC

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
75442-47030			NAME PLATE (PRUIS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
75374-47051			NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
75310-47020			EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
76801-47070-B0			TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
58307-47060			END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
51442-12210			UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
58308-47011			UNDER COVER SUB-ASSY. RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
76891-47020			BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
76087-47020			BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Check <input checked="" type="checkbox"/>
76088-47020			BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
52591-47021			BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
52592-47021			BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given <input checked="" type="checkbox"/>
<b>Total</b>					<b>\$4,640.90</b>		<b>\$120.00</b>		

  

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

120.00 /  
- 20%

96.00 /  
+ 200.00 /  
+ 576.88 /

872.88 /

4/3 \$850/- ✓

3 days