

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305424311
 REGN NO : SHA3884X
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 18.06.2015
 DATE/TIME IN : 23.09.2020 15:15
 ACCIDENT DATE : 23.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76	de ✓
0002 04-01-0103-0637-G	I40VC BRKT ASSY-FR BPR UP	1	22.40	20.00	17.92	X un ✓
0003 04-01-0103-0639-G	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68	X un ✓
0004 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	de ✓
0005 04-01-0103-0574-G	I40VC PANEL-FENDER LH#	1	663.00	20.00	530.40	Rx ✓
0006 04-01-0103-2834-A	I40V3 GUARD ASSY-FRONT WH	1	174.90	20.00	139.92	de ✓
0007 04-01-0103-0781-A	I40VC LAMP ASSY-HEAD LH#	1	1,388.00	20.00	1,110.40	unt ✓
0008 04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	112.50	20.00	90.00	unt ✓

2199.68

SUB-TOTAL : 2,767.68

JOB NATURE

0000 L	PANEL BEATING	600.00	420
0001 23-502	SPRAYPAINT ON AFFECTED AREA	450.00	400
0002 17-01	CHECK ALL LIGHTING	50.00	30

Tanpin 97445749
 WP 27/1/20 (2) 3 days
 L/S Resurvey after repair
 Tanpin 164 auto m -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65208755

JOB NO : 305424311
REGN NO : SHA3884X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 18.06.2015
DATE/TIME IN : 23.09.2020 15
ACCIDENT DATE : 23.09.2020

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00		30		
0004 20-08	ADJUST FRONT WHEEL ALIGNMENT	80.00		60		940
SUB-TOTAL :						1,230.00
TOTAL :						3,997.68

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

2199.68
940
3139.68

4/5/2500
2days