

TAT HENG MOTOR WORKS

BLK 10, ANG MO KIO IND PK 2A
02-09 AMK AUTOPOINT
SINGAPORE 568047
TEL : 6483 7103 FAX : 6481 7732

THIRD PARTY CLAIM

VEHICLE NO : SDV1095G

MODEL : HARRIER ELEGANCE 2.0 A

CHASSIS : ZSU600051619

Not Authorised
11/09 @ 1650h
Kennerth Pichay After Paint
1st 96910663
2 days
Kennerth Keng e/kkauto.com

No	Qty	Description	U/Price	Amount	
1	1	Rear bumper	<i>RM</i> 1,386.00	1,386.00	<i>2</i>
2	1	Rear bumper inner sponge	<i>CM</i> 118.00	118.00	<i>2</i>
3	2	Rear bumper side bracket	59.00	<i>1</i> 118.00	<i>X</i>
4	2	Rear bumper bracket	51.00	<i>1</i> 102.00	<i>X</i>
5	2	Rear bumper reflector	39.00	<i>1</i> 78.00	<i>X</i>
6	1	Rear bumper lower cover	<i>RM</i> 318.00	318.00	<i>1</i>
				2,120.00	
Less <i>20% 25%</i>				424.00	
				1,696.00	
Nett Item					
9	1 set	Rear bumper clip		<i>RM</i> 35.00	<i>1</i>
10	1 set	Bootlid inner trim clip		<i>RM</i> 35.00	<i>X</i>
11	1 set	Reverse sensor		<i>RM</i> 250.00	<i>2005</i>
12		To check wiring for proper function including remove and refix reverse sensor.		<i>501</i> 150.00	
13		To replace, repair, straighten & re-align all damaged parts.		<i>2001</i> 450.00	
14		To spray paint on all affected areas		<i>2201</i> 500.00	
Total :				3,116.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 2 by Repairer

Signature:

Date: