



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TOH MENG TIAK (DU MINGZHE) Reg No/Reg Date SMD9942Y*ECB / 14/09/201 Date In/Mileage 23/09/2020/ 0 Chassis No KNAF3416MK5015071 Engine No G4FGJH707254 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/09/2020/ 10:49	BLC	442 / CocoLu	21567			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								400.00
RENEW FRT BUMPER,								350.00
E PNT98000								50.00
SPRAY PAINT FOR FRT BUMPER								2400 4000.00
M SUNDRY								
FRT NUMBER PLATE WITH FRAME								
E PNT88000								60.00
RENEW REAR BUMPER, REAR END PANEL, REAR COMPARTMENT								
BOOTLID,								
E PNT88000								160 200.00
REMOVE & INSTALL PARKING SENSOR								
E PNT88000								1400 1750.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS AND SEATS								
E PNT98000								
SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, REAR COMPARTMENT								
BOOTLID,								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								80 120.00
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								40.00
C&C LOGO								
A 90000001								? 200.00
RENEW EXHAUST SYSTEM								
M SUNDRY								220.00
SUPPLY PARKING SENSOR								
M COVER-FR BUMPER de /					1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER					1.00	262.00	20.00	209.60
M COVER-FR BUMPER FOG LAMP,RH X					1.00	15.00	20.00	12.00
M COVER-FR BUMPER FOG LAMP,LH X					1.00	15.00	20.00	12.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or the rubber seal or other repair requiring the removal of the windscreen.



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TOH MENG TIAK (DU MINGZHE) Reg No/Reg Date SMD9942Y*ECB / 14/09/201 Date In/Mileage 23/09/2020/ 0 Chassis No KNAF3416MK5015071 Engine No G4FGJH707254 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/09/2020/ 10:49	BLC	442 / CocoLu	21567			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	GRILLE ASSY-RADIATOR	ca			1.00	328.00	20.00	262.40
M	MOULDING-FRONT BUMPER, RH				1.00	36.00	20.00	28.80
M	MOULDING-FRONT BUMPER, LH				1.00	36.00	20.00	28.80
M	ABSORBER-FRONT BUMPER ENERGY				1.00	84.00	20.00	67.20
M	COVER-RR BUMPER	de			1.00	651.00	20.00	520.80
M	COVER-RR BUMPER LWR	ca			5.00	241.00	20.00	964.00
M	COVER-RR BUMPER UNDER, LH				1.00	33.00	20.00	26.40
M	COVER-RR BUMPER FOG LAMP, RH	can			1.00	19.00	20.00	15.20
M	COVER-RR BUMPER FOG LAMP, LH	X			1.00	19.00	20.00	15.20
M	LAMP ASSY-SIDE T/SIGNAL, RH				1.00	181.00	20.00	144.80
M	LAMP ASSY-SIDE T/SIGNAL, LH				1.00	181.00	20.00	144.80
M	EXTN WIRING ASSY-BWS				1.00	207.00	20.00	165.60
M	BRACKET-RR BEAM UPR MTG, RH				1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM UPR MTG, LH				1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM LWR, CTR				1.00	6.00	20.00	4.80
M	BRACKET-RR BEAM LWR MTG				2.00	6.00	20.00	9.60
M	BEAM-RR BUMPER				1.00	318.00	20.00	254.40
M	ANTENNA ASSY-SMARTKEY				1.00	46.00	20.00	36.80
M	STAY-RR BUMPER RH				1.00	65.00	20.00	52.00
M	STAY-RR BUMPER LH				1.00	65.00	20.00	52.00
M	BRACKET-ASSY RR BPR SIDE UPR, R				1.00	31.00	20.00	24.80
M	BRACKET-ASSY-RR BPR SIDE UPR, L				1.00	25.00	20.00	20.00
M	PANEL ASSY-TRUNK LID	repair			1.00	1297.00	20.00	1037.60
M	PANEL ASSY-BACK	st			1.00	324.00	20.00	259.20
M	LOGO ASSY-KIA SUB	ren			1.00	32.00	20.00	25.60
M	EMBLEM-CERATO	ren			1.00	28.00	20.00	22.40
M	W/STRIP-TRUNK LID OPNG	X			1.00	100.00	20.00	80.00
M	LATCH ASSY-TRUNK LID	X			1.00	112.00	20.00	89.60
M	PANEL ASSY-REAR FLOOR, RR	st			1.00	219.00	20.00	175.20
M	TRIM ASSY-RR TRANSVERSE				1.00	41.00	20.00	32.80
M	MAT ASSY-LUGGAGE COVERING				1.00	211.00	20.00	168.80
M	PROTECTOR-HEAT REAR	st			1.00	136.00	20.00	108.80
M	MUFFLER ASSY-REAR				1.00	757.00	20.00	605.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Rasul-Hp 90010068

SURVEYOR SIGNATURE: [Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys are not allowed
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

DATE: 24/09/2020 @ 1650

REMARKS:

13 days

EXCESS: TBA / REPAIR

7% GST on

Nett

13738.40

13,738.40

961.69

Total Payable

14,700.09

Authorized signatory and company stamp

Repair before paint

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.