



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance and Mitsubishi vehicle information.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: KAX00008, Credit, 24/09/2020/ 11:44, QUD, 247 / DonBong, 57731

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair items like 'RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL' and 'PAINT WORK SPRAY FRONT SUPPORT PANEL'.

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV11583/SHAWN ANG AH SENG
	Reg No/Reg Date	SMM3996J / 27/06/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0601698
	Engine No	4J11BD7303
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	24/09/2020/ 11:44	QUD	247 / DonBong	57731

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GRILLE ASSY,RADIATOR <i>scd ? xsv</i>	1.00	548.00	23.00	421.96
M BRACKET,FR BUMPER SIDE,LH <i>? xsv</i>	1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,RH <i>? xsv</i>	1.00	18.00	23.00	13.86
M FACE,FR BUMPER <i>scd ? xsv</i>	1.00	859.00	23.00	661.43
M COVER,FR BUMPER <i>scd ? xsv</i>	1.00	359.00	23.00	276.43
M GARNISH,FR BUMPER SIDE <i>? xsv</i>	1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE <i>? xsv</i>	1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER SIDE <i>? xsv</i>	1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE <i>? xsv</i>	1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE <i>? xsv</i>	1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER SIDE <i>? xsv</i>	1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER,LH <i>? xsv</i>	1.00	48.00	23.00	36.96
M GARNISH,FR BUMPER,RH <i>? xsv</i>	1.00	48.00	23.00	36.96
M EXTENSION,FR BUMPER <i>scd ? xsv</i>	1.00	515.00	23.00	396.55
M CLIP,FR BUMPER <i>scd ? xsv</i>	10.00	4.00	23.00	30.80
M REINFORCEMENT,FR BUMPER <i>? xsv</i>	1.00	490.00	23.00	377.30
M REINF,FR BUMPER SIDE,RH <i>? xsv</i>	1.00	69.00	23.00	53.13
M REINFORCEMENT,FR BMRP SIDE <i>? xsv</i>	1.00	22.00	23.00	16.94
M REINF,FR BUMPER SIDE,LH <i>? xsv</i>	1.00	60.00	23.00	46.20
M BODY KIT, OUTLANDER <i>? xsv</i>	1.00	1554.00	20.00	1243.20

Estimate

SURVEYOR NAME: Rosal - 4p 9001068

SURVEYOR SIGNATURE: [Signature]

DATE: 25/09/2020 @ 1430

REMARKS: 5 days

REPAIR / EXCESS: TBA

Resy before print

Confirm & accepted by

	Nett	12,776.31
7% GST on	12776.31	894.34
Total Payable		13,670.65

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

CAR NO: 5MM 3996J

WIP: 57731

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	REINFORCEMENT FR BUMPER SIDE RH	? / SUPP		✓	6400D582
2	REINFORCEMENT FR BUMPER	? / SUPP		✓	6400G574
3	REINFORCEMENT FR BUMPER	? / SUPP		✓	6400J626
4	HEAD LAMP ASSY RH	? / SUPP		✓	8301D930
5	FACE FR BUMPER	? / SUPP		✓	6400K786
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	5/10	
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: OUTLANDER 2.0

SURVEYOR: RASUL @ LKX



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMM 3996 J

<u>Materials</u>		<u>Cost \$</u>
1	Reinforcement, FR Bumper bt ✓	134.00
	23% Discount	30.82
		<hr/>
		103.18
	7% GST	7.22
	Total	<hr/> 110.40

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens