



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV12507/CHNG CHANG CHING
	Reg No/Reg Date	SMQ8280L / 03/12/201
	Date In/Mileage	/ 3598
	Chassis No	MMBSTA13AKH003684
	Engine No	3A92UJC5550
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	24/09/2020/ 11:37	QUD	247 / DonBong	57737			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER, RH FRONT FENDER, RH SIDE MIRROR, REPAIR FRONT BONNET								1125 2250.00
E PNT88000 REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK								100.00
A 55900099 TOP UP AIR CON GAS AND CHECK A/CON SYSTEM								80.00
E PNT98000 PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT BODY KIT, RH FRONT FENDER, RH SIDE MIRROR AND AFFECTED PORTION								1575 2450.00
M SUNDRY APPLY BODY KITS SEALANT								60.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
M SUNDRY PERFORM RUST PREVENTION								80.00
M SUNDRY SUPPLY FRONT NUMBER PLATE WITH FRAME								50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
A 3900099 RENEW FRONT UNDERCARRIAGE DAMAGES								450.00
M SUNDRY LABOUR RENEW RH FRONT SPORT RIM INCLUDING BALANCING WHEEL ALIGNMENT BP								30.00
To Conduct Computerize Full Wheel Alignment								120.00
M SUNDRY SUNDRIES								50.00
MIRROR ASSY, DOOR, RH X 300					1.00	638.00	23.00	491.26

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<tr> <td>Cust No/Name</td><td>KCV12507/CHNG CHANG CHING</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMQ8280L / 03/12/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 3598</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AKH003684</td></tr> <tr> <td>Engine No</td><td>3A92UJC5550</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>PO1 RED METALLIC / BK BLACK</td></tr>	Cust No/Name	KCV12507/CHNG CHANG CHING	Reg No/Reg Date	SMQ8280L / 03/12/201	Date In/Mileage	/ 3598	Chassis No	MMBSTA13AKH003684	Engine No	3A92UJC5550	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	PO1 RED METALLIC / BK BLACK
Cust No/Name	KCV12507/CHNG CHANG CHING														
Reg No/Reg Date	SMQ8280L / 03/12/201														
Date In/Mileage	/ 3598														
Chassis No	MMBSTA13AKH003684														
Engine No	3A92UJC5550														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	PO1 RED METALLIC / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	24/09/2020/ 11:37	QUD	247 / DonBong	57737
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M COVER, DOOR MIRROR, OTR RH <i>? XSVL</i>		1.00	114.00	23.00	87.78
M FENDER, FR RH <i>bt</i>		1.00	497.00	23.00	382.69
M EMBLEM ECO <i>de</i>		1.00	17.00	00.00	17.00
M SHIELD, FR WHEELHOUSE, RH <i>de</i>		1.00	98.00	23.00	75.46
M CLIP, FENDERSHIELD <i>de</i>		10.00	4.00	23.00	30.80
M HEADLAMP ASSY, RH <i>cm</i>		1.00	660.00	23.00	508.20
M PANEL, HEADLAMP SUPPORT, UPR <i>XSVL</i>		1.00	65.00	23.00	X 50.05
M PANEL ASSY, FR END <i>XSVL</i>		1.00	1055.00	23.00	X 812.35
M GRILLE, RADIATOR <i>XSVL</i>		1.00	554.00	23.00	X 426.58
M MARK, THREE-DIA <i>XSVL</i>		1.00	69.00	23.00	X 53.13
M BRACKET, FR BUMPER, LH <i>XSVL</i>		1.00	13.00	23.00	X 10.01
M BRACKET, FR BUMPER, RH <i>? XSVL</i>		1.00	13.00	23.00	X 10.01
M GRILLE, FR UNDER <i>XSVL</i>		1.00	165.00	23.00	X 127.05
M GARNISH, FR BUMPER, RH <i>de</i>		1.00	127.00	23.00	97.79
M AIR DAM, SIDE, FR RH <i>XSVL</i>		1.00	18.00	23.00	X 13.86
M AIR DAM, SIDE, FR LH <i>XSVL</i>		1.00	18.00	23.00	X 13.86
M COVER, HEADLAMP SUPT PANEL <i>XSVL</i>		1.00	62.00	23.00	X 47.74
M CLIP, FR BUMPER <i>de</i>		10.00	4.00	23.00	30.80
M COVER, FR BUMPER <i>de</i> <i>? XSVL</i>		1.00	13.00	23.00	X 10.01
M FACE, FR BUMPER <i>de</i>		1.00	703.00	23.00	541.31
M BODY KIT, ATTRAGE, W54 <i>cm</i>		1.00	1643.00	00.00	1643.00
M WHEEL, DISC <i>sc</i>		1.00	687.00	23.00	528.99
M GEAR & LINK ASSY, STEERING <i>? XSVL</i>		1.00	1444.00	23.00	X 1111.88
M LH END ASSY, TIE ROD <i>? XSVL</i>		1.00	52.00	23.00	X 40.04
M RH END ASSY, TIE ROD <i>? XSVL</i>		1.00	52.00	23.00	X 40.04
M STRUT, FR SUSP <i>? XSVL</i>		1.00	452.00	23.00	348.04
M PAD, FR SUSP SPRING <i>? XSVL</i>		1.00	17.00	23.00	13.09
M SEAT, FR SUSP SPRING, UPR <i>? XSVL</i>		1.00	37.00	23.00	28.49
M BEARING, FR SUSP STRUT <i>? XSVL</i>		1.00	9.00	23.00	6.93
M SUPPORT, FR SUSP STRUT <i>? XSVL</i>		1.00	17.00	23.00	13.09
M INSULATOR, FR SUSP STRUT <i>? XSVL</i>		1.00	83.00	23.00	63.91
M INSULATOR, FR SUSP STRUT <i>? XSVL</i>		1.00	98.00	23.00	75.46
M HUB ASSY, FR WHEEL <i>? XSVL</i>		1.00	215.00	23.00	165.55

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr><td>Cust No/Name</td><td>KCV12507/CHNG CHANG CHING</td></tr> <tr><td>Reg No/Reg Date</td><td>SMQ8280L / 03/12/201</td></tr> <tr><td>Date In/Mileage</td><td>/ 3598</td></tr> <tr><td>Chassis No</td><td>MMBSTA13AKH003684</td></tr> <tr><td>Engine No</td><td>3A92UJC5550</td></tr> <tr><td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr><td>Colour/Trim</td><td>P01 RED METALLIC / BK BLACK</td></tr> </table>	Cust No/Name	KCV12507/CHNG CHANG CHING	Reg No/Reg Date	SMQ8280L / 03/12/201	Date In/Mileage	/ 3598	Chassis No	MMBSTA13AKH003684	Engine No	3A92UJC5550	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	P01 RED METALLIC / BK BLACK
Cust No/Name	KCV12507/CHNG CHANG CHING														
Reg No/Reg Date	SMQ8280L / 03/12/201														
Date In/Mileage	/ 3598														
Chassis No	MMBSTA13AKH003684														
Engine No	3A92UJC5550														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	P01 RED METALLIC / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	24/09/2020/ 11:37	QUD	247 / DonBong	57737			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	SNAP RING,FR WHEEL HUB	2. neu			1.00	8.00	23.00	6.16
M	BEARING,FR WHEEL HUB	2. bt			1.00	121.00	23.00	93.17
M	COVER,FR BRAKE DISC	2. xsu			1.00	26.00	23.00	20.02
M	KNUCKLE,RH	2. bt			1.00	365.00	23.00	281.05
M	ARM ASSY,FR SUSP,LWR RH	2. bt			1.00	337.00	23.00	259.49
M	CROSSMEMBER,FR AXLE,NO.1	2. bt			1.00	864.00	23.00	665.28
M	SHAFT AS,FR AXLE DRIVE,RH	2. xsu			1.00	1201.00	23.00	924.77

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME : Rasul - 475001008

SURVEYOR SIGNATURE : RA

DATE : 24/09/2020 @ 1645

REMARKS : 6 days

EXCESS: TBA / Repair

Resy before paint

Confirm & accepted by

7% GST on	Nett 16036.19	16,036.19
		1122.53
Total Payable		17,158.72

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.