

Date: 21.09.2020
Vehicle No: SLF3259C
Model: TOYOTA SIENTA
Chassis: NSP1707012739
Reg.Year: 2016

Not Authorised
11 Sep 8
Recovery After Pain

Third Party Insurer: EQ
Third Party Veh No: SKZ1238H
Date of Accident: 27.03.2020

ESTIMATE

4 days

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>R1</i> \$1,281.90 ✓
2	REAR TAILGATE INNER LOCK	1		<i>R</i> \$158.60 X
3	REAR TAILGATE INNER TRIM	1		<i>R</i> \$287.50 X
4	REAR TAILGATE INNER TRIM CLIPS	1		<i>nn</i> \$35.00 X
5	REAR TAILGATE TOYOTA EMBLEM	1		<i>nn</i> \$58.70 ✓
6	REAR WINDSCREEN MOULDING	2	\$90.20	<i>nn</i> \$180.40 ✓
7	REAR END PANEL	1		<i>R</i> \$533.80 X
8	REAR END PANEL UPPER COVERING	1		<i>nn</i> \$165.80 ✓
9	REAR END PANEL UPPER COVERING CLIPS	1		<i>nn</i> \$25.00 X
10	REAR BUMPER	1		<i>R</i> \$587.20 X
11	REAR BUMPER ABOSRBER FOAM	1		<i>R</i> \$87.20 X
12	REAR BUMPER CENTER	1		SVC \$240.00 X
13	REAR BUMPER SIDE LH	1		<i>R</i> \$179.70 X
14	REAR BUMPER SIDE RH	1		<i>R</i> \$179.70 X
SUB TOTAL				\$4,000.50
LESS 25%				-\$1,000.13
PARTS TOTAL				\$3,000.38

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>nn</i> \$80.00 <i>400m</i>
2	REAR WINDSCREEN STOPPER	2	\$15.00	<i>R</i> \$30.00 <i>1</i>
3	REAR NUMBER PLATE WITH HOLDER	1		<i>R</i> \$45.00
4	REVERSE SENSOR	1		<i>nn</i> \$220.00 <i>200m</i>
S/N TOTAL				\$375.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST REAR ACCIDENT AREAS & ETC. \$700.00 *350*

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE. \$150.00 *120*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR TAILGATE. \$120.00 *60*

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 21.09.2020
 Vehicle No: SLF3259C
 Model: TOYOTA SIENTA
 Chassis: NSP1707012739
 Reg.Year: 2016

Third Party Insurer: EQ
 Third Party Veh No: SKZ1238H
 Date of Accident: 27.03.2020

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL, REAR FLOOR PANEL & ETC.	\$600.00	40d
TO TUFF KOTE & UNDERSEAL MATERIALS	\$120.00	30d
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$80.00	15d

LABOUR TOTAL	\$1,770.00
--------------	------------

VIC	TOTAL	\$5,145.38
-----	-------	------------

