

AIG INSURANCE

|                |                   |
|----------------|-------------------|
| Vehicle number | SF5898E           |
| Make / Model   | BMW 730i          |
| Chassis number | WBAKB22030C951400 |
| Accident date  | 22/9/20           |
| Reference      | 2009-28           |

| Qty                                   | Particulars                                    | Unit Price - SGD \$ |          |
|---------------------------------------|------------------------------------------------|---------------------|----------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u> |                                                |                     |          |
| 1                                     | FRONT BUMPER <i>Dented</i>                     | 1805.50 ✓           | 1765.90  |
| 2                                     | FRONT BUMPER RETAINER <i>src</i>               | 64.00 X             |          |
| 1                                     | FRONT BUMPER SIDE GRILLE RH <i>HL</i>          | 92.00 X             |          |
| 1                                     | FRONT BUMPER CENTRE GRILLE <i>HL</i>           | 132.00 X            |          |
| 1                                     | FRONT BUMPER TOW COVER <i>HL</i>               | 63.25 X             |          |
| 1                                     | FRONT BUMPER FOG LAMP RH <i>HL</i>             | 380.00 X            |          |
| 1                                     | FRONT BUMPER FOG LAMP COVER RH <i>HL</i>       | 150.20 X            |          |
| 1                                     | FRONT NOZZLE <i>HL</i>                         | 218.50 X            |          |
| 1                                     | FRONT NOZZLE COVER <i>HL</i>                   | 63.25 X             |          |
| 1                                     | BONNET <i>HL</i>                               | 3447.70 X           |          |
| 1                                     | BONNET WEATHERSTRIP <i>HL</i>                  | 66.00 X             |          |
| 2                                     | BONNET HINGE <i>HL</i>                         | 218.50 X            |          |
| 1                                     | FRONT HEADLAMP RH <i>&amp; mainly broken</i>   | 3312.00 ✓           | 135.20   |
| 1                                     | FRONT HEADLAMP BRACKET RH <i>HL crack</i>      | 304.75 X ✓          | 1171.85  |
| 1                                     | FRONT FENDER RH <i>Dented</i>                  | 1426.00 ✓           |          |
| 1                                     | FRONT FENDER INNER SHIELD RH <i>&amp; torn</i> | 163.30 ✓            |          |
| 1                                     | FRONT FENDER CHROME GARNISH RH <i>&amp; rt</i> | 161.00 ✓            |          |
| 1                                     | FRONT RH LOWER ARM <i>&amp; distorted</i>      | 743.00 ✓            | 618.20   |
| 1                                     | FRONT RH UPPER ARM <i>&amp; distorted</i>      | 598.00 ✓            |          |
| 1                                     | FRONT RH CONTROL ARM <i>&amp; distorted RA</i> | 586.50 ✓            |          |
| 1                                     | FRONT RH SHOCK ABSORBER <i>&amp; distorted</i> | 1598.50 ✓           | 1385.65  |
| 1                                     | FRONT RH KNUCKLE ARM <i>&amp; distorted</i>    | 770.50 ✓            | 662.70   |
| 1                                     | FRONT RH KNUCKLE ARM BEARING <i>&amp; Down</i> | 563.50 ✓            | 484.50   |
| 1                                     | STEERING RACK <i>HL</i>                        | 7843.00 X           |          |
| 1                                     | STABILISING BAR <i>HL</i>                      | 563.50 X            |          |
| 1                                     | CROSSMEMBER <i>HL</i>                          | 2231.00 X           |          |
| 1                                     | FRONT RH SIDE SKIRT <i>broken</i>              | 615.25 ✓            |          |
| 1                                     | REAR RH DOOR PANEL <i>st</i>                   | 3335.00 ✓           | 2193.20  |
| 1                                     | REAR RH DOOR LOCK ASSY <i>HL</i>               | 805.00 X            |          |
| 1                                     | REAR RH DOOR REGULATOR MOTOR <i>HL</i>         | 379.50 X            |          |
| 1                                     | REAR RH DOOR INNER TRIM BOARD <i>HL</i>        | 517.50 X            |          |
| 1                                     | REAR RH DOOR HANDLE <i>HL</i>                  | 686.55 X            |          |
| 1                                     | REAR RH DOOR WEATHERSTRIP <i>HL</i>            | 264.50 X            |          |
| 1                                     | REAR RH FENDER <i>Dented</i>                   | 4393.00 ✓           | 1812.45  |
| 1                                     | REAR RH FENDER INNERSHIELD <i>HL</i>           | 207.00 X            |          |
| 1                                     | REAR RH LOWER ARM <i>HL</i>                    | 287.50 X            |          |
| 1                                     | REAR RH UPPER TRAILING ARM <i>HL</i>           | 696.90 X            |          |
| 1                                     | REAR RH KNUCKLE ARM <i>HL</i>                  | 1506.50 X           |          |
| 1                                     | REAR RH KNUCKLE ARM BEARING <i>HL</i>          | 224.24 X            |          |
| 1                                     | REAR RH SHOCK ABSORBER <i>HL</i>               | 3760.50 X           |          |
|                                       |                                                | 45214.39            | 15665.70 |
| 10% Less 5%                           |                                                | 2260.72             | 14099.13 |
|                                       |                                                | 42953.67            |          |

| PARTS REPLACEMENT - SPECIAL NETT ITEMS |                                                 |                |
|----------------------------------------|-------------------------------------------------|----------------|
| 2                                      | RIM o/s front cut o/s rear repair               | 1600.00 ✓      |
| 2                                      | TYRE HH                                         | 1200.00 X      |
| 1 BOT                                  | BRAKE FULID HH                                  | 60.00 X        |
| 1 SET                                  | FRONT BUMPER CLIP HH                            | 40.00 30/-     |
| 1 SET                                  | FRONT RH INNER SHIELD CLIP HH                   | 50.00 15/-     |
| 1 SET                                  | FRONT BUMPER GRILLE CLIP HH                     | 40.00 X        |
| 1 SET                                  | RH SIDE SKIRT CLIP HH                           | 80.00 15/-     |
| 1 SET                                  | REAR RH DOOR INNER TRIM CLIP HH                 | 50.00 X        |
| 1 SET                                  | REAR RH INNER SHIELD CLIP HH                    | 50.00 X        |
| 1 PC                                   | FRONT BUMPER SENSOR HH                          | 400.00 X       |
| Subtotal                               |                                                 | 3570.00        |
| Balance C/F                            |                                                 | 46523.67       |
| LABOUR AND MISCELLANEOUS CHARGES       |                                                 |                |
| Balance B/F                            |                                                 | 46523.67       |
| 1                                      | CHECK WIRING AND LIGHTNING SYSTEM               | 60.00 30/-     |
| 2                                      | COMPUTERISED AND CHECK F & R WHEEL ALIGNMENT    | 300.00 60/-    |
| 3                                      | REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS    | 200.00 180/-   |
| 4                                      | REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS     | 200.00 HH      |
| 5                                      | REMOVE AND REPLACE REAR RH DOOR PANEL           | 150.00 80/-    |
| 6                                      | REMOVE AND REPLACE FRONT BONNET                 | 150.00 HH      |
| 7                                      | REMOVE AND REFIT FUEL TANK TO FACILITATE REPAIR | 300.00 HH      |
| 8                                      | PANEL BEATING ON AFFECTED AREAS                 | 2600.00 1200/- |
| 9                                      | SPRAY PAINTING ON AFFECTED AREAS                | 2400.00 1000/- |
| 10                                     | APPLY ANTI RUST ON AFFECTED AREAS               | 150.00 40/-    |
| Subtotal                               |                                                 | 6510.00        |
| Grand total                            |                                                 | 53033.67       |

800/-

860.00 =

2590.00 =

24/09/2020 @ 1600hrs


Not Authorised

2/Share 9 days.

17549.13

R/S 11,000/-

yan Check part prices  
LKK Auto Check MV repair limit.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: