

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 24.09.20

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLT1387E**
MODEL : **TOYOTA C-HR HYBRID**
DATE OF ACCIDENT : 24.09.20
TIME OF ACCIDENT : 08:10HRS

Justin.

ZYX102069999

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Del'd</i>	1	\$ 889.80	\$ 889.80
2	FRONT BUMPER FOGLAMP RH <i>crack'd</i>	1	\$ 505.20	\$ 505.20
3	FRONT BUMPER FOGLAMP HOUSING RH <i>crack'd</i>	1	\$ 371.70	\$ 371.70
4	FRONT BUMPER UPPER GRILLE <i>crack'd</i>	1	\$ 439.60	\$ 439.60
5	FRONT BUMPER LOWER GRILLE <i>crack'd</i>	1	\$ 98.50	\$ 98.50
6	FRONT BUMPER BOTTOM COVER GARNISH <i>for</i>	1	\$ 185.30	\$ 185.30
7	FRONT BUMPER TOP COVER GARNISH <i>Del'd</i>	1	\$ 160.50	\$ 160.50
8	FRONT BUMPER LOWER BEAM <i>del Best</i>	1	\$ 130.10	\$ 130.10
9	FRONT BUMPER SIDE RETAINER <i>del</i>	2	\$ 78.50	\$ 157.00
10	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 467.40	\$ 467.40
11	FRONT BUMPER SPONGE <i>crack'd</i>	1	\$ 177.80	\$ 177.80
12	FRONT NUMBER PLATE GARNISH <i>crack'd</i>	1	\$ 85.90	\$ 85.90
13	FRONT FENDER INNER COWLING <i>RH torn</i>	2	\$ 239.30	\$ 478.60
14	FRONT FENDER ARCD GARNISH <i>new</i>	2	\$ 148.50	\$ 297.00
15	GRILLE LOGO <i>not in</i>	1	\$ 1,673.50	\$ 1,673.50
16	GRILLE LOGO GARNISH BASE <i>crack'd</i>	1	\$ 83.10	\$ 83.10
17	GRILLE LOGO GARNISH <i>new</i>	1	\$ 105.30	\$ 105.30
18	HEADLAMP (LED) <i>RH crack'd</i>	2	\$ 4,396.80	\$ 8,793.60
19	FRONT MILLIMETER WAVE RADAR <i>new</i>	1	\$ 1,256.80	\$ 1,256.80
20	HORN <i>not in</i>	1	\$ 85.10	\$ 85.10
21	AIR DUCT <i>crack'd</i>	1	\$ 138.30	\$ 138.30
22	FRONT WASHER TANK <i>Del'd</i>	1	\$ 268.50	\$ 268.50
23	FRONT WASHER TANK MOTOR <i>new</i>	1	\$ 164.30	\$ 164.30
24	REAR BUMPER (UPPER) <i>Del'd</i>	1	\$ 586.30	\$ 586.30
25	REAR BUMPER (LOWER) <i>Del'd</i>	1	\$ 499.30	\$ 499.30
26	REAR BUMPER TOW HOOK COVER <i>RH crack'd</i>	1	\$ 18.20	\$ 18.20
27	REAR BUMPER REFLECTOR GARNISH <i>RH</i>	2	\$ 89.20	\$ 178.40

at

354.

239.50

4396.80 2721

89.20

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLT1387E**
 MODEL : **TOYOTA C-HR HYBRID**
 DATE OF ACCIDENT : 24.09.20
 TIME OF ACCIDENT : 08:10HRS

28	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 333.20	\$ 333.20	✓
29	REAR BUMPER SIDE RETAINER <i>per</i>	2	\$ 100.40	\$ 200.80	✓
30	TAILGATE <i>Dented</i>	1	\$ 1,204.70	\$ 1,204.70	✓
31	TAILGATE DAMPER <i>new</i>	2	\$ 262.20	\$ 524.40	+
32	TAILGATE OUTER GARNISH <i>crushed</i>	1	\$ 891.20	\$ 891.20	✓
33	TAILGATE SIDE LAMP <i>RT crushed</i>	2	\$ 358.90	\$ 717.80	358.90
34	TAIL GATE LOGO <i>per</i>	1	\$ 80.30	\$ 80.30	✓
35	TAILGATE EMBLEM 'C-HR' <i>per</i>	1	\$ 52.90	\$ 52.90	✓
36	TAILGATE EMBLEM 'HYBRID' <i>per</i>	1	\$ 65.70	\$ 65.70	✓
37	TAILGATE INNER HOLDER <i>per</i>	1	\$ 85.30	\$ 85.30	+
38	TAILGATE STOPPER <i>per</i>	2	\$ 24.50	\$ 49.00	+
39	TAILGATE TOP LOCK <i>Damaged</i>	1	\$ 385.70	\$ 385.70	✓
40	TAILGATE LOWER LOCK <i>new</i>	1	\$ 38.50	\$ 38.50	+
41	TAILGATE DETECTOR <i>crushed</i>	1	\$ 367.20	\$ 367.20	✓
42	TAILGATE INNER TRIM <i>crushed</i>	1	\$ 386.70	\$ 386.70	✓
43	TAILGATE WEATHER STRIP <i>lit</i>	1	\$ 325.10	\$ 325.10	✓
44	TAILGATE WINDSCREEN MOULDING (SET) <i>per</i>	1	\$ 133.70	\$ 133.70	✓
45	TAIL LAMP <i>RT crushed</i>	2	\$ 443.20	\$ 886.40	443.20
46	TAIL LAMP SIDE GARNISH <i>gap</i>	2	\$ 86.50	\$ 173.00	+
47	TAIL LAMP LOWER BRACKET <i>gap</i>	2	\$ 52.80	\$ 105.60	+
48	REAR FENDER INNER TRIM <i>RT crushed</i>	2	\$ 386.70	\$ 773.40	386.70
49	REAR FENDER COWLING <i>RT torn</i>	2	\$ 184.60	\$ 369.20	184.60
50	REAR FENDER ARCED GARNISH <i>per</i>	2	\$ 143.70	\$ 287.40	+
51	REAR END PANEL <i>Dented</i>	1	\$ 694.70	\$ 694.70	✓
52	REAR END PANEL TOP GARNISH <i>crushed</i>	1	\$ 246.80	\$ 246.80	✓
53	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 625.70	\$ 625.70	385
54	REAR TOOLS SPONGE <i>Dented</i>	2	\$ 176.50	\$ 353.00	✓
55	REAR EXHAUST PIPE <i>Dented</i>	1	\$ 1,478.20	\$ 1,478.20	987
56	REAR EXHAUST INSULATOR <i>gap</i>	1	\$ 141.70	\$ 141.70	+
57	REAR EXHAUST MOUNTING <i>gap</i>	6	\$ 35.70	\$ 214.20	+
58	REAR EXHAUST GASKET (SET) <i>de</i>	1	\$ 32.10	\$ 32.10	✓

16660
12495

TOTAL PRICE \$ 30,518.70
 LESS 25% \$ 7,629.68
SUB TOTAL PRICE \$ 22,889.03

SPECIAL NETT ITEMS

SPECIAL NETT ITEMS				
S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE (SPECIAL TYPE) <i>Crushed</i>	1	\$ 150.00	\$ 150.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLT1387E**
 MODEL : **TOYOTA C-HR HYBRID**
 DATE OF ACCIDENT : 24.09.20
 TIME OF ACCIDENT : 08:10HRS

2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT BUMPER FOG LAMP RING (SET) (SPECIAL TYPE) <i>new</i>	1	\$ 380.00	\$ 380.00	x
4	FRONT BUMPER LED LIGHT (SPECIAL TYPE) <i>121 changed</i>	1	\$ 450.00	\$ 450.00	200
5	FRONT BUMPER CHROME MOULDING (SPECIAL TYPE) <i>lit</i>	1	\$ 250.00	\$ 250.00	150
6	REAR BUMPER LED LIGHT (CENTER) (SPECIAL TYPE) <i>cut</i>	1	\$ 300.00	\$ 300.00	120
7	REAR BUMPER DIFFUSER (SPECIAL TYPE) <i>Dislodged</i>	1	\$ 550.00	\$ 550.00	380
8	REAR BUMPER SIDE LED LIGHT (SET) (SPECIAL TYPE) <i>RH cut</i>	1	\$ 350.00	\$ 350.00	200
9	REAR BUMPER SIDE LED LIGHT COVER (CARBON FIBER) (SET) (SPECIAL TYPE) <i>new</i>	1	\$ 480.00	\$ 480.00	+ 180
10	FRONT NUMBER PLATE GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	10
11	FRONT FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	20
12	FRONT FENDER ARCD GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
13	GRILLE LOGO GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
14	REAR NUMBER PLATE (SPECIAL TYPE) <i>new</i>	1	\$ 150.00	\$ 150.00	+
15	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
16	REAR BUMPER CENTER CARBON STICKER (SPECIAL TYPE) <i>new</i>	1	\$ 180.00	\$ 180.00	60
17	REAR BUMPER CENTER CHROME MOULDING (SPECIAL TYPE) <i>best</i>	1	\$ 380.00	\$ 380.00	100
18	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	20
19	TAILGATE INNER TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
20	TAILGATE LAMP TOP COVRE (CARBON FIBRE) (SPECIAL TYPE) <i>new</i>	2	\$ 480.00	\$ 960.00	50
21	TAILGATE OUTER TOP GARNISH (SPECIAL TYPE) <i>new</i>	1	\$ 450.00	\$ 450.00	150
22	TAILGATE WINDSCREEN SEALANT <i>2 per</i>	1	\$ 80.00	\$ 80.00	40
23	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	40
24	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
25	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	20
26	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
27	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
28	REAR END PANEL TOP CHROME (SPECIAL TYPE) <i>new</i>	1	\$ 550.00	\$ 550.00	+
29	REVERSE SENSOR (SET) <i>new</i>	1	\$ 220.00	\$ 220.00	20
30	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	x 2190
TOTAL			\$	7,250.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	300
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	200

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLT1387E**
 MODEL : **TOYOTA C-HR HYBRID**
 DATE OF ACCIDENT : 24.09.20
 TIME OF ACCIDENT : 08:10HRS

3	REFOCUS HEADLAMP BEAM	\$ 80.00	30
4	REMOVE AND RESET MILLIMETER WAVE RADAR	\$ 120.00	2

530

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	1000
3	TUFF COAT	\$ 250.00	60
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	60
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	80
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

2300

TOTAL \$ 7,870.00

TOTAL PARTS COST : \$ 30,139.03
 TOTAL LABOUR COST : \$ 7,870.00
 TOTAL REPAIR COST : \$ 38,009.03

Adnan
 H/s 25/09/20
 09 Days
 Total: 17515
 H/s: 14K

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

Nett Value : 16K