

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0697/2020/NS
DATE : 26-Sep-20
WIP : 50665

Asher.

26561.20.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : YM 6777 M

LONPAC INSURANCE BHD

100 BEACH ROAD

#19-00 SHAW TOWER

SINGAPORE 189702

Attn: Motor Claims Dept

Fax: 6296 2706

OWNER'S NAME : DR WONG CHONG YU KELVIN
ADDRESS : 9B MARLENE AVENUE
SINGAPORE 556621
TELEPHONE : HP +65 81265822
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800022575
VEHICLE NO : SLW 9160 Z
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 8/3/2018
ENGINE NO : CVK 052310
CHASSIS NO : WAUZZZF41JA086181
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Sep-20
PLACE OF ACCIDENT : 6 MARLENE AVE 556612



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 9160 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N	\$ 360.00 ✓	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N	\$ 280.00 ✓	✓
3	TO RENEW REAR WINDSCREEN AND LHS REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N	\$ 600.00 ✓	✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS REAR 1/4 GLASS.	S/N	\$ 400.00 ✓	✓
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N	\$ 200.00 ✓	✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 1,840.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 9160 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00 ✓	✓
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAGS ETC.	S/N \$ 1,400.00 ✓	✓
8	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	4900 $5,600.00$	$7 \times 700 = 4900$ ✓
9	TO REPSRAY REAR BUMPER, REAR LID, HINGES, LHS REAR FENDER, DOOR ENTRANCES, LHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	3850 $5,650.00$	$700 \times 5.5 = 3850$ ✓
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 16,082.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPOKE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 9160 Z

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER Repair deformed		\$ 2,181.00 ✓		2,181.00
2 REAR BUMPER FIXING PARTS		\$ 72.00 ✗		
3 REAR BUMPER SECURING STRIP		\$ 220.00 ✗		
4 REAR BUMPER SPOILER		\$ 246.00 ✗		
5 REAR LIGHT REFLECTOR - LH REAR		\$ 41.00 ✗		
6 LED TAIL LIGHT - LH		\$ 1,008.00 ✓		1,008.00
7 TAIL LIGHT TRIM- LH		\$ 30.00 ✓		29.20
8 LED TAIL LIGHT - LH		\$ 1,008.00 ✓		1,008.00
9 TAIL LIGHT TRIM - LH		\$ 30.00 ✓		21.90
10 REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 44.00 ✗		
11 REAR BUMPER GUIDE SECTION - LH		\$ 44.00 ✗		
12 REAR PARKING AID SENSOR - INNER / OUTER	2	TBC ✓		
13 REAR PARKING AID SEAL RING	4	\$ 14.00 ✗		
14 REAR LID Dented.		\$ 2,623.00 ✓		2,623.00
15 REAR LID HINGE - LH / RH	2	\$ 452.00 ✗		
16 REAR LID ATTACHMENT PARTS		\$ 144.00 ✗		
17 REAR LID FLAP GASKET Repair nec		\$ 203.00 ✓		202.50
18 PACKING ADHESIVE		\$ 18.00 ✓		18.00
19 AUDI EMBLEM		\$ 122.00 ✓		122.00
20 A4 INSCRIPTION		\$ 95.00 ✓		94.20
SUB TOTAL SPAKE PARTS		\$ 8,595.00		

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 9160 Z

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 TFSI INSCRIPTION <i>2 New</i>		\$ 95.00	✓	94.20
22 REAR FENDER - LH <i>Buckled</i>		\$ 2,644.00	✓	2,644.00
23 REAR WINDSCREEN <i>Rec</i>		\$ 1,141.00	✓	1,141.00
24 SIDE WINDOW - LH <i>New</i>		\$ 609.00	✓	608.50
25 PRIMER <i>New</i>		\$ 19.00	✓	18.70
26 REAR NO PLATE <i>Not in</i>	S/N	\$ 60.00	X	
27 REAR WINDSCREEN SEALANT <i>2 New</i>	S/N	\$ 200.00	✓	200.00
28 1/4 GLASS SEALANT	S/N	\$ 100.00	✓	100.00
29 METAL FILLER POWDER <i>Rec</i>	S/N	\$ 280.00	✓	180.00 280.00
30 STONE CHIP <i>2</i>	S/N	\$ 180.00	✓	180.00
31 CAVITY WAX <i>New</i>	S/N	\$ 140.00	✓	140.00
32 ACRYLIC SEALANT <i>New</i>	S/N	\$ 180.00	✓	180.00
33 SUNDRIES		\$ 350.00	?	85.00
TOTAL SPARE PARTS	:	\$ 14,593.00		
TOTAL LABOUR CHARGES	:	\$ 16,082.00		
GRAND TOTAL	:	\$ 30,675.00		

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME : *Adrian*
SURVEYED DATE : *29/09/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 13 Days*
H.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT