

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20010275/ABA3Q2

Date: 07/04/2021

REFERENCE

| | | | | |
|---|-----------------------------|---------------|-----------------|--|
| Handling Insurer: India International Insurance Pte Ltd | Policy No: | D19MFL0005549 | | |
| Claimant Vehicle No : SLC9761U | Insured Vehicle No : | GBH195E | | |
| Date of Loss: 24/09/2020 | Nature of Claim: TP | Claim No: | MFL2020D0001887 | |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SLC9761U | | |
| Make & Model: | HYUNDAI ELANTRA, 1.6 AD GLS (A) | Engine No: | G4FGGU188952 |
| Reg. Date: | 31/05/2016 (Man. Year: 2016) | Chassis No: | KMHD841CMHU195164 |
| Colour: | Blue | Odometer: | 80490 km |
| Engine Capacity: | 1591 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------|------------------|------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Nexen 6 mm | Rear Left Side: | Nexen 6 mm |
| Front Right Side: | Nexen 6 mm | Rear Right Side: | Nexen 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-----------------|-----------------|-----------------|--------------|
| Parts | 4,987.82 | 4,205.65 | 782.17 | 15.68 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,940.00 | 1,890.00 | 1,050.00 | 35.71 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 7,927.82 | 6,095.65 | 1,832.17 | 23.11 |
| + GST 7.00/7.00% (S\$) | 554.95 | 426.70 | 128.25 | 23.11 |
| Nett Amount (S\$) | 8,482.77 | 6,522.35 | 1,960.42 | 23.11 |
| + Loss of Use (6.0 x S\$80.00/day) (S\$) | | 480.00 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 7,009.80 | | |
| Global Sum Settlement (S\$) | | 6,800.00 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 25/09/2020 | |
| Date Inspected: | 25/09/2020 Inspected At: | People's Vehicle Recovery Service (HQ) Blk 3023A Ubi Rd 1, #01-60 Singapore 408717 |
| Estimated Period of Repair: | 6.0 days | |

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|----------------------------|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 03 Mar 2021) |
| Parts: 143 | HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLC9761U) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *DOOR R/H REAR | Distorted | 1,878.36 FL | *1,878.36 FL |
| 2 | 1 | | *DOOR INNER LOCK R/H REAR | Not Necessary | 363.20 FL | *- FL |
| 3 | 1 | | *DOOR RUBBER R/H REAR | Not Necessary | 116.20 FL | *- FL |
| 4 | 1 | | *DOOR BLACK TAPE R/H REAR | Necessary | 96.00 FL | *96.00 FL |
| 5 | 1 | | *FENDER R/ H REAR | Distorted | 1,982.00 FL | *1,982.00 FL |
| 6 | 1 | | *FENDER INNER SHIELD R/H REAR | Torn | 118.30 FL | *118.30 FL |
| 7 | 1 | | *MUDGUARD FLAP REAR R/H | Missing | 86.30 FL | *86.30 FL |
| 8 | 1 | | *TAIL LAMP R/H | Cracked | 368.00 FL | *368.00 FL |
| 9 | 1 | | *BUMPER REAR | Distorted | 459.40 FL | *459.40 FL |
| 10 | 1 | | *BUMPER SIDE RETAINER R/H REAR | Necessary | 44.30 FL | *44.30 FL |
| 11 | 1 | | *BUMPER REFLECTOR R/H REAR | Not Necessary | 89.20 FL | *- FL |
| 12 | 1 | | *DOOR STICKER TAPE R/H REAR | Repeated | 45.30 FL | *- FL |
| 13 | 1 | | *ROCKER PANEL STICKER TAPE R/H | Necessary | 48.20 FL | *48.20 FL |
| 14 | 1 | | *FENDER INLET AIR GARNISH L/H REAR | Deformed | 126.20 FL | *126.20 FL |
| 15 | 1 | | *WINDSCREEN GUM | Necessary | 40.00 FS | *40.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 5,860.96 | 5,247.06 |
| - List Item Discount on L Items 15.00/20.00% (\$) | 873.14 | 1,041.41 |
| Total Parts (\$) | 4,987.82 | 4,205.65 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | REMOVE & REPLACE ACCIDENT DAMAGED PARTS | New | 1,400.00 | 900.00 |
| 2 | SPRAY PAINTING ACCIDENT EFFECTED PARTS | New | 900.00 | 700.00 |
| 3 | REMOVE AND REFIT REAR UPHOLSTERY CARPET AND ETC | New | 260.00 | 60.00 |
| 4 | CHECK REAR WIRING AND LIGHTING OPERATION | New | 60.00 | 30.00 |
| 5 | COMPUTERIZED WHEEL ALIGNMENT | New | 80.00 | 0.00 |
| 6 | REMOVE AND REFIX WINDSCREEN REAR | New | 120.00 | 120.00 |
| 7 | UNDERCOAT | New | 120.00 | 80.00 |
| Gross Labour Cost (\$) | | | 2,940.00 | 1,890.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >