

# PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717

Tel No. : 67433246 / 67438552 Fax No. : 67430013

E-Mail : peoplevehicle@gmail.com

Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street #04/#05

IOB Building (S) 049711

Attention : Motor Claim Department

Contact : 63476100 Fax No. : 62244174

*Jasper.*

Estimate : ES20023

Date : 25/09/2020

Vehicle Num. : SLC 9761 U

Make/Model : HYUNDAI ELANTRA

Chassis/Eng# :

Accident Date : 25/09/2020

Claim No. : TP 386-20

Reference : GBH 195 E

Policy No. : NTUC 511760358

| S/N                      | Quantity | Particular                                      | Unit Price | Amount S\$ |
|--------------------------|----------|---|------------|------------|
| LIST ITEMS :             |          |   |            |            |
| 1.                       | 1        | DOOR R/H REAR <i>Dislud</i>                     |            | 1,878.36 ✓ |
| 2.                       | 1        | DOOR INNER LOCK R/H REAR <i>new</i>             |            | 363.20 ✗   |
| 3.                       | 1        | DOOR RUBBER R/H REAR <i>new</i>                 |            | 116.20 ✗   |
| 4.                       | 1        | DOOR BLACK TAPE R/H REAR <i>new</i>             |            | 96.00 ✓    |
| 5.                       | 1        | FENDER R/H REAR <i>Dislud</i>                   |            | 1,982.00 ✓ |
| 6.                       | 1        | FENDER INNER SHIELD R/H REAR <i>new</i>         |            | 118.30 ✓   |
| 7.                       | 1        | MUDGUARD FLAP REAR R/H <i>Missing</i>           |            | 86.30 ✓    |
| 8.                       | 1        | TAIL LAMP R/H <i>new</i>                        |            | 368.00 ✓   |
| 9.                       | 1        | BUMPER REAR <i>Dislud</i>                       |            | 459.40 ✓   |
| 10.                      | 1        | BUMPER SIDE RETAINER R/H REAR <i>new</i>        |            | 44.30 ✓    |
| 11.                      | 1        | BUMPER REFLECTOR R/H REAR <i>new</i>            |            | 89.20 ✗    |
| 12.                      | 1        | DOOR STICKER TAPE R/H REAR <i>Repaired</i>      |            | 45.30 ✗    |
| 13.                      | 1        | ROCKER PANEL STICKER TAPE R/H <i>new</i>        |            | 48.20 ✗    |
| 14.                      | 1        | FENDER INLET AIR GARNISH L/H REAR <i>Rehard</i> |            | 126.20 ✓   |
| List Total S\$ :         |          |   | 5207.06    | 5,820.96   |
| 15.00% Discount S\$ :    |          |   |            | 873.14     |
| <i>20%</i>               |          |   | 4165.64    | 4,947.82   |
| SPECIAL NETT ITEMS :     |          |   |            |            |
| 1.                       | 1        | WINDSCREEN GUM <i>new</i>                       |            | 40.00 ✓    |
| Special Nett Total S\$ : |          |   | 40         | 40.00      |

KMH0841CMHUIS164

CONTINUE / ...

# PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717  
 Tel No. : 67433246 / 67438552 Fax No. : 67430013  
 E-Mail : peoplevehicle@gmail.com  
 Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

**INDIA INTERNATIONAL INSURANCE PTE LTD**  
 64 Cecil Street #04/#05  
 IOB Building (S) 049711

Attention : Motor Claim Department  
 Contact : 63476100 Fax No. : 62244174

**Estimate : ES20023**

Date : 25/09/2020  
 Vehicle Num. : SLC 9761 U  
 Make/Model : HYUNDAI ELANTRA  
 Chassis/Eng# :  
 Accident Date : 25/09/2020  
 Claim No. : TP 386-20  
 Reference : GBH 195 E  
 Policy No. : NTUC 511760358

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

LABOUR :  
 REMOVE & REPLACE ACCIDENT DAMAGED PARTS  
 SPRAY PAINTING ACCIDENT EFFECT PARTS  
 REMOVE AND REFIT REAR UPHOLSTERY, CARPET AND ETC.  
 CHECK REAR WIRING AND LIGHTING OPERATION  
 COMPUTERIZED WHEEL ALIGNMENT  
 REMOVE AND REFIX WINDSCREEN REAR  
 UNDERCOAT

1890

|                     |          |
|---------------------|----------|
| <del>1,480.00</del> | 900      |
| <del>900.00</del>   | 700      |
| <del>260.00</del>   | 60       |
| 50.00               | 30       |
| 80.00               | x        |
| 120.00              | ✓        |
| <del>120.00</del>   | 80       |
| <hr/>               |          |
|                     | 2,940.00 |

Labour Total S\$ :

SingDollars : Seven Thousand Nine Hundred Twenty-Seven & Cents Eighty-Two Only

E. & O.E.

Total S\$ : 7,927.82

for PEOPLE'S VEHICLE RECOVERY SERVICE

Computer Generated Invoice. No Signature Required.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Adnan G  
 P/P 25/09/20  
 06 Days

total: 6093.64  
 (P/P)