



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name /Ezrein Shah Bin Selamat
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date SME9496M*ECB / 24/10/201
78 SHENTON WAY #08-16	Date In/Mileage / 0
AIG BUILDING	Chassis No KNAF3416MK5019120
SINGAPORE 079120	Engine No G4FGJH710275
Contact No 64191000	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/09/2020/ 14:51	BLC	442 / CocoLu	21629			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW FRT BUMPER, FRT FENDER RH, BONNET, FRT SUPPORT PANEL								1000
REPAIR FRT DOOR RH								
E PNT98000								1750.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH, FRT DOOR RH								1400
E PNT88000								100.00
REMOVE & INSTALL AIRCON								12X?
M SUNDRY								80.00
TOP UP AIRCON GAS								12X?
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								40.00
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								20.00
Sundry								
M COVER-FR BUMPER					1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER					1.00	262.00	20.00	209.60
M COVER-FR BUMPER FOG LAMP, RH					1.00	15.00	20.00	12.00
M GRILLE ASSY-RADIATOR					1.00	328.00	20.00	262.40
M MOULDING-FRONT BUMPER, RH					1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER, RH					1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER, RH					1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	20.00	67.20
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	22.00	20.00	17.60
M PANEL ASSY-HOOD					1.00	1502.00	20.00	1201.60
M PANEL-FENDER, RH					1.00	430.00	20.00	344.00
M GUARD ASSY-FRONT WHEEL, RH					1.00	95.00	20.00	76.00
M BEAM COMPLETE-FR BUMPER					1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	20.00	540.00
M LAMP ASSY-HEAD, RH					1.00	1219.00	20.00	975.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Ezrein Shah Bin Selamat
	Reg No/Reg Date	SME9496M*ECB / 24/10/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5019120
	Engine No	G4FGJH710275
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/09/2020/ 14:51	BLC	442 / CocoLu	21629			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	RESERVOIR & PUMP ASSY-WASHER 7. de ✓				1.00	146.00	20.00	116.80
M	GUARD-AIR, RH 7.45 ✓				1.00	28.00	20.00	22.40
M	CONDENSER ASSY-COOLER 7.45 ✓				1.00	687.00	20.00	549.60
M	RADIATOR ASSY 7.45 ✓				1.00	646.00	20.00	516.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Rasul - Hp 90010068SURVEYOR SIGNATURE: [Signature]DATE: 25/09/2020 @ 1040REMARKS: 5 daysRepair / excess-TBARepair before paint

Confirm & accepted by

Nett 10,109.60
7% GST on 10109.60 707.67

Total Payable 10,817.27

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renew the rubber seal or other repair requiring the removal of the windscreen.