

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nadaraja, Deeban

Date: 25 Sep 2020

Preliminary Advice

Vehicle No	: SKF6655J	Accident Date	: 02/09/2020
Make	: AUDI Q5	Policy No.	: 2100303401
Assignment Date	: 25/09/2020	Excess	: S\$0.00
Date of Inspection	: 24/09/2020	Est. Duration of Repair	: 5
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,434.00
Revised Amount	:S\$	12,141.00
Check Items (Estimated)	:S\$	607.00
Total	:S\$	12,748.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	51,500.00
COE / PARF Rebate	:S\$	39,671.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,829.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. Margin for repair is \$ 11,829.00, repairer able to undertake the repair cost not exceeding \$ 11,500.00.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :