



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr><td>Cust No/Name</td><td>/GAJENDRA SUNDAR KARTHIK</td></tr> <tr><td>Reg No/Reg Date</td><td>SME1566Y / 20/09/201</td></tr> <tr><td>Date In/Mileage</td><td>/ 0</td></tr> <tr><td>Chassis No</td><td>MMBSTA13AJH003161</td></tr> <tr><td>Engine No</td><td>3A92UHG6509</td></tr> <tr><td>Make/Model</td><td>MIT/18MY ATTRAGE 1.2 CVT</td></tr> <tr><td>Colour/Trim</td><td>U01 TITANIUM GREY M/ BK BLACK</td></tr> </table>	Cust No/Name	/GAJENDRA SUNDAR KARTHIK	Reg No/Reg Date	SME1566Y / 20/09/201	Date In/Mileage	/ 0	Chassis No	MMBSTA13AJH003161	Engine No	3A92UHG6509	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK
Cust No/Name	/GAJENDRA SUNDAR KARTHIK														
Reg No/Reg Date	SME1566Y / 20/09/201														
Date In/Mileage	/ 0														
Chassis No	MMBSTA13AJH003161														
Engine No	3A92UHG6509														
Make/Model	MIT/18MY ATTRAGE 1.2 CVT														
Colour/Trim	U01 TITANIUM GREY M/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	24/09/2020/ 15:59		442 / CocoLu	57753
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW REAR BUMPER, REAR END PANEL, REAR AIRDAM, SPOILER BOOTLID, REPAIR REAR FENDER RH & LH	1800	2250.00		405000.00
E PNT88000	REMOVE & INSTALL BODY KIT	60	100.00		6000.00
E PNT88000	REMOVE & INSTALL PARKING SENSOR		60.00		60.00
E PNT88000	REMOVE & INSTALL REAR COMPARTMENT TRIMS	120	200.00		24000.00
E PNT98000	SPRAY PAINT FOR REAR AIRDAM, REAR BUMPER, REAR END PANEL REAR FENDER RH & LH, BOOTLID, SPOILER	2275	2800.00		637000.00
M SUNDRY	APPLY SEALANT FOR ACCIDENT PORTION	80	120.00		9600.00
M SUNDRY	C&C LOGO		40.00		40.00
M SUNDRY	REAR NUMBER PLATE WITH FRAME	1	50.00		50.00
M SUNDRY	Sundry		20.00		20.00
A 54900099	CHECK WIRING & ELECTRICAL SYSTEM		30.00		30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST		120.00		120.00
M BODY KIT ATTRAGE, TITANLUM GREY, U17		1.00	1643.00	20.00	1314.40
M FACE, RR BUMPER		1.00	748.00	23.00	575.96
M BRACKET, RR BUMPER, RH		1.00	28.00	23.00	21.56
M BRACKET, RR BUMPER, LH		1.00	28.00	23.00	21.56
M PANEL, RR END		1.00	425.00	23.00	327.25
M WEATHERSTRIP, TRUNK LID		1.00	157.00	23.00	120.89
M PANEL, TRUNK LID		1.00	791.00	23.00	609.07
M HINGE, TRUNK LID, RH		1.00	203.00	23.00	156.31

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /GAJENDRA SUNDAR KARTHIK Reg No/Reg Date SME1566Y / 20/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003161 Engine No 3A92UH6509 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	24/09/2020/ 15:59		442 / CocoLu	57753
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M HINGE, TRUNK LID, LH ? xsv		1.00	203.00	23.00	156.31
M LATCH, TRUNK LID ? xsv		1.00	218.00	23.00	167.86
M GARNISH, RR END PANEL de		1.00	336.00	23.00	258.72
M MARK, THREE-DIA re		1.00	69.00	23.00	53.13
M MARK, ATTRAGE re		1.00	21.00	23.00	16.17
M TRIM, RR END ? xsv		1.00	66.00	23.00	50.82
M BOARD, TRUNK ROOM FLOOR ca		1.00	195.00	23.00	150.15
M REFLECTOR x sv		1.00	23.00	23.00	17.71
M REFLECTOR x sv		1.00	23.00	23.00	17.71
M LAMP ASSY, LICENSE PLATE ? xsv		1.00	51.00	23.00	39.27
M BUZZER, KEYLESS OPERATIO, RR ? xsv		1.00	91.00	23.00	70.07
M ANT, KEYLESS OPERATION, RR ? xsv		1.00	96.00	23.00	73.92
M DUCT, RR VENTILATOR ? xsv		1.00	30.00	23.00	23.10
M COVER, RR VENTILATOR ? xsv		1.00	40.00	23.00	30.80

SURVEYOR NAME: Ram - 4p 90010068SURVEYOR SIGNATURE: [Signature]DATE: 28/09/2020 @ 1100REMARKS: 8 daysRenew / EXCESS: TBARenew before part

Confirm & accepted by

Net 10,062.74
 7% GST on 10062.74 704.39
 Total Payable 10,767.13

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.