

. 1077014600

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

CST Peg No . MP_8500111_Y

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV01710/LIM JOO YONG			
Ltd.	Reg No/Reg Date	SMR3113P / 18/11/201			
MOTOR CLAIM DEPT	Date In/Mileage	/ 0			
78 SHENTON WAY #08-16	Chassis No	JMAXTGK1WLZ000609			
AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Engine No	4B40HB0394			
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C STYLE SR			
	Colour/Trim	DOO LIGHTNING BLUE / BK BLACK			

Account No	Terms	Date/Time Pri	inted	CSE	Operator		WIP No	- 10 T	THE RESERVE
KAX00008	Credit	24/09/2020/	16:26	QUD	247 / DonBong		57754		
AL STREET		Description	of Good	s / Service	S	Qty	Unit Price	Disc%	Amount /
E PNT88000 REMOVE AN E PNT88000 REMOVE AN TO FACILI A 55900099 TOP UP AI E PNT98000 PAINT WOF	ND INSTAL IND INSTAL ITATE REF IR CON GA RK SPRAY FENDER,	AMAGED PARTS RH FRONT F LL PARKING AS LL A/CON COND PAIR WORK AS AND CHECK FRONT SUPPOR LH FRONT FEN	ON FRONTENDER, F	T SUPPORT REPAIR RH ND RADIATO	PANEL, FRONT DOOR	990	450 ×2	(3	$900 \frac{2250.00}{60.00}$ 60.00 100.00 100.00 100.00
SUNDRY	ING AND	CHASSIS ELECT	TRICAL S	SYSTEM				1	11×80.00 30.00 11×80.00
APPLY BOD 10028901 TO CARRY OUSING HI-S	OUT DIAG	NOSTIC CHECK	USING H	II-SCAN PR	O TEST				120.00
SUNDRY	ONT NUMBE	ER PLATE WITH	I FRAME	4/					50.00 N 50.00
PANEL, HEAD PANEL, HEAD PANEL, AIR	LAMP SUP MP SUPT, LAMP SUP GUIDE SI	UPR RH ? X A PORT, UPR 2 X PORT, LWR X DE, RH 2 X A	250			1.00 1.00 1.00 1.00	171.00 59.00 219.00	23.00	45.43 131.67 45.43 168.63 63.14
PANEL, AIR	CHIDE ST	DE 1117 VA	1			1.00	82.00	SAN (10) 5474021	63.14

: Site Insp

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Type: M.Cdr / M.Cycle / Bus / Van



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

Estimated Cost

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

Co Reg No : 197701469G

AIG BUILDING

SINGAPORE 079120

Contact No 6419 1892

GST Reg No : MR-8500111-X Invoice Name & Address Owner Name & Vehicle Info Cust No/Name AIG Asia Pacific Insurance Pte. KCV01710/LIM JOO YONG Reg No/Reg Date SMR3113P / 18/11/201 MOTOR CLAIM DEPT Date In/Mileage 78 SHENTON WAY #08-16

JMAXTGK1WLZ000609 Engine No 4B40HB0394 Make/Model

Chassis No

MIT/ECLIPSE CROSS 1.5 T/C STYLE SR Colour/Trim DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
KAX00008	Credit	24/09/2020/ 16:26	QUD	247 / DonBong		57754		
		Description of Goods	/ Services	BETTE BUTTER	Qty	Unit Price	Disc%	Amount
M CONDENSER	ASSY, A/	C REFRIGE ! XAA			1.00	701.00	23.00	
M LLC 4L	? Xn	7/1			1.00		23.00	539.7
M COVER, FR	BUMPER G	RILLE ? KAT			1.00	302.00		20.02
M GRILLE AS	SY, RADIA	TOR ? XAA			1 00	484.00		232.54
M CLIP, FR B	UMPER ~	7 7.	LKK Auto	Consultants hence notify	10.00		23.00	372.68
M BRKT,F/BM	PR T/SIG	LAMP, LH ? fin	the Repa	irer of the following:	1.00	17.00		30.80
M BRKT,F/BM	PR T/SIG	LAMP, RH ? KAL	 To resurv 	ey before/after spray painting	1 00			13.09
M FACE, FR B			 To display 	damaged part(s) during resurve	1.00	17.00 714.00		13.09
COVER, FR	BUMPER C	w/	Parts price	es are subject to confirmation	1 00	380.00		549.78
EXTENSION	FR BUMP	ER SCA!	Third part	y survey is on a "Without Prejud	i.00			292.60
LH GARNISI	FR BUM	PER SIDE CA	• No illegal	modification(s) is allowed		317.00		244.09
RH GARNISI	FR BUM	PER SIDE COL	Suppleme	ntary item(s) must be resurveye to final eaprovel from insurante	1.00	214.00	23.00	164.78
LH GARNISH	,FR BUMP	PER SIDE 7 XAN	- Indicate	o mayapprova nomansuranse	1.00	214.00		164.78
RH GARNISH REINFORCEM	FR BUMF	PER SIDE CAL	Acknowledg	ed by Repairer ()	4.60	73.00		56.21
REINFORCEM	ENT, FR E	SUMPER ? YOU	Signature:	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.00	77.00		59.29
BAR, FR BUM	PER GUAR	o? Kun	Date:		1.00	552.00		425.04
BRACKET, FR	BUMPER	SIDE, LH ? XAA			1.00	100.00	23.00	77.00
BRACKET, FR	BUMPER	SIDE, RH ? XAA	1151			18.00		13.8
LH CTR SEN	SOR, FWD	DISTANCE WARNIN MAN	? dis/		1.00	18.00		13.86
RH CTR SEN	OR, FWD	DISTANCE WARNIN . 3.	AN XSVC		1.00	329.00	23.00	253.33
LH SENSOR,	ORNER CI	EARANCE XSUC			1.00	329.00		253.33
RH SENSOR,	ORNER CL	EARANCE L SVC			1.00	329.00	23.00	253.33
HEADLAMP AS	SY, LH ?	XSVC "			1.00	329.00		253.33
HEADLAMP AS	SY, RH C	1			1.00	1976.00	23.00	1521.52
LAMP A, T/SI	G & FOG.	FR LH X 12			1.00	1976.00	23.00	1521.52
LAMP A.T/SI	G & FOG.	FR RH 7 KAA			1.00	506.00	23.00	389.63
FRONT BUMPFI	GARNIS	H? ciut/			1.00	506.00	23.00	389.62
FRONT CORNER	FXTENS	ION 7. LSIL			1.00	384.00		295.68
FENDER FR RE	readir				1.00	238.00		183.20
PAD, FR FENDE	07		Q_{α}	1. 11. 9	1.00	599.00		461.23
THOU TENDE	". XV	SURVEYOR	VAME: 19	Su 49 900 100 18	1.00	57.00		43.8
							23.00	43.0
		SURVEYOR S	SIGNATURE	: 4	-			
	ell_ll_ ?	, 	29/00	2020 @ 1020				
firm & accep	ted by	DATE:						
		REMARKS:		5 days				14,828.2
		KEIWANNO:	1	. DA		Net		20 25
		Revol	I ELLE	AS: 6A 7	GST on	14620.3		1023.4
			Description	y before paint	Tot	tal Payable		
			TORUNIO	OR TANK THE THREE TO	10	a Pavable	2	15,643.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or the rubber seal or other repair requiring the removal of the windscreen in the event of inadvertent breakage in the course of renewing



INSURANCE CO.: AIG

Supplementary For Registration No.: SMR 3113 P

	Materials		Cost \$
1 2	Reinforcement, FR Bumper bt Reinf, FR Bumper Side, RH bt		235.00 35.00
	rteini, i it bamper side, itti bt		270.00
		23% Discount	62.10
			207.90
		7% GST	14.55
		Total	222.45

Thank You.

Yours faithfully CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan Customer Service Cycle & Carriage Pandan Gardens