



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV01710/LIM JOO YONG Reg No/Reg Date SMR3113P / 18/11/201 Date In/Mileage / 0 Chassis No JMAXTGK1WLZ000609 Engine No 4B40HB0394 Make/Model MIT/ECLIPSE CROSS 1.5 T/C STYLE SR Colour/Trim DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	24/09/2020/ 16:26	QUD	247 / DonBong	57754			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000					@450 X 2			900 2250.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER FACE, RH FRONT FENDER, REPAIR RH FRONT DOOR								60.00
E PNT88000								? 100.00
REMOVE AND INSTALL PARKING ASSIST								? 80.00
E PNT88000								1050 2100.00
REMOVE AND INSTALL A/CON CONDENSER AND RADIATOR TO FACILITATE REPAIR WORK								X 80.00
A 55900099								30.00
TOP UP AIR CON GAS AND CHECK A/CON SYSTEM								X 80.00
E PNT98000					@350 X 3			120.00
PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BUMPER FACE, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR AND AFFECTED PORTION								50.00
M SUNDRY								20 50.00
PERFORM RUST PREVENTION								
A 54900099								
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
M SUNDRY								
APPLY BODY SEALANT								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
M SUNDRY								
SUPPLY FRONT NUMBER PLATE WITH FRAME								
M SUNDRY								
SUNDRIES								
M	PNL, HEADLAMP SUPT, UPR RH				1.00	59.00	23.00	45.43
M	PANEL, HEADLAMP SUPPORT, UPR				1.00	171.00	23.00	131.67
M	PNL, HEADLAMP SUPT, UPR LH				1.00	59.00	23.00	45.43
M	PANEL, HEADLAMP SUPPORT, LWR				1.00	219.00	23.00	168.63
M	PANEL, AIR GUIDE SIDE, RH				1.00	82.00	23.00	63.14
M	PANEL, AIR GUIDE SIDE, LH				1.00	82.00	23.00	63.14

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV01710/LIM JOO YONG Reg No/Reg Date SMR3113P / 18/11/201 Date In/Mileage / 0 Chassis No JMAXTGK1WLZ000609 Engine No 4B40HB0394 Make/Model MIT/ECLIPSE CROSS 1.5 T/C STYLE SR Colour/Trim DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	24/09/2020/ 16:26	QUD	247 / DonBong	57754

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M CONDENSER ASSY,A/C REFRIGE ?	1.00	701.00	23.00	539.77
M LLC 4L ?	1.00	26.00	23.00	20.02
M COVER,FR BUMPER GRILLE ?	1.00	302.00	23.00	232.54
M GRILLE ASSY,RADIATOR ?	1.00	484.00	23.00	372.68
M CLIP,FR BUMPER ?	1.00	4.00	23.00	30.80
M BRKT,F/BMPR T/SIG LAMP,LH ?	1.00	17.00	23.00	13.09
M BRKT,F/BMPR T/SIG LAMP,RH ?	1.00	17.00	23.00	13.09
M FACE,FR BUMPER ?	1.00	714.00	23.00	549.78
M COVER,FR BUMPER ?	1.00	380.00	23.00	292.60
M EXTENSION,FR BUMPER ?	1.00	317.00	23.00	244.09
M LH GARNISH,FR BUMPER SIDE ?	1.00	214.00	23.00	164.78
M RH GARNISH,FR BUMPER SIDE ?	1.00	214.00	23.00	164.78
M LH GARNISH,FR BUMPER SIDE ?	1.00	73.00	23.00	56.21
M RH GARNISH,FR BUMPER SIDE ?	1.00	77.00	23.00	59.29
M REINFORCEMENT,FR BUMPER ?	1.00	552.00	23.00	425.04
M BAR,FR BUMPER GUARD ?	1.00	100.00	23.00	77.00
M BRACKET,FR BUMPER SIDE,LH ?	1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,RH ?	1.00	18.00	23.00	13.86
M LH CTR SENSOR,FWD DISTANCE WARNIN ?	1.00	329.00	23.00	253.33
M RH CTR SENSOR,FWD DISTANCE WARNIN ?	1.00	329.00	23.00	253.33
M LH SENSOR,CORNER CLEARANCE ?	1.00	329.00	23.00	253.33
M RH SENSOR,CORNER CLEARANCE ?	1.00	329.00	23.00	253.33
M HEADLAMP ASSY,LH ?	1.00	1976.00	23.00	1521.52
M HEADLAMP ASSY,RH ?	1.00	1976.00	23.00	1521.52
M LAMP A,T/SIG & FOG,FR LH ?	1.00	506.00	23.00	389.62
M LAMP A,T/SIG & FOG,FR RH ?	1.00	506.00	23.00	389.62
M FRONT BUMPER GARNISH ?	1.00	384.00	23.00	295.68
M FRONT CORNER EXTENSION ?	1.00	238.00	23.00	183.26
M FENDER,FR RH ?	1.00	599.00	23.00	461.23
M PAD,FR FENDER ?	1.00	57.00	23.00	43.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from insurance

Acknowledged by Repairer
Signature: _____
Date: _____

SURVEYOR NAME: Resue - 499000068

SURVEYOR SIGNATURE: [Signature]

DATE: 29/09/2020 @ 10:20

REMARKS: 5 days

Confirm & accepted by _____

Authorized signatory and company stamp _____

Nett	14,620.38
14620.38	1023.43
Total Payable	15,643.81

Remarks: Resurvey before paint

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.