

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Sep 2020		05 Oct 2020 17:49 Edit Adj Rpt	S\$9,500.00 Edit Estimates	S\$9,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HONG MENG LANDSCAPE PTE LTD , Co. Reg. No.: 201009098M		
Main Claimant:	LIM SENG SANG , ID: S0177696G		
Vehicle Reg. No.:	SMK4497L	Date of Loss:	23/09/2020 17:00 - :59 [17 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM20D203515/C02/TKL	Policy/Cover Note No.:	DMCVSN30461619055
Vehicle Reg. No. (Insured):	GP9690G	Policy No. (Claimant):	VPA/P2276809
		Excess:	S\$0.00
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/10/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMK4497L (SNM20D203515/C02/TKL)**
[GP9690G]
TP
LIM SENG SANG
Sep 23 2020 5:00PM
[HONG MENG LANDSCAPE PTE LTD]
RICO 60 AUTO SERVICES PTE LTD

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports					
				1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print
1	24/09/20 15:46	Accident Statement		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/10/20 16:16	Adjuster Immediate Advice		Load HTM	
Photos/Images					
				3 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print
1	24/09/20 15:43	Driving License [Linked Accident Report Documents]		Load JPG	☒
2	24/09/20 15:43	Insurance Cert [Linked Accident Report Documents]		Load JPG	☒
3	24/09/20 15:43	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	24/09/20 15:43	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	24/09/20 15:43	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	24/09/20 15:43	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	24/09/20 15:43	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	24/09/20 15:43	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/10/20 08:02	Chassis Number		Load JPG	☒
2	12/10/20 08:02	Odometer Reading		Load JPG	☒
3	12/10/20 08:04	General View		Load JPG	☒
4	12/10/20 08:04	General View		Load JPG	☒
5	12/10/20 08:04	General View		Load JPG	☒
6	12/10/20 08:04	General View		Load JPG	☒
7	12/10/20 08:04	General View		Load JPG	☒
8	12/10/20 08:04	General View		Load JPG	☒
9	12/10/20 08:04	General View		Load JPG	☒
10	12/10/20 08:04	General View		Load JPG	☒
11	12/10/20 08:04	General View		Load JPG	☒
12	12/10/20 08:04	General View		Load JPG	☒
13	12/10/20 08:04	General View		Load JPG	☒
14	12/10/20 08:04	General View		Load JPG	☒
15	12/10/20 08:04	General View		Load JPG	☒
16	12/10/20 08:04	General View		Load JPG	☒
17	12/10/20 08:04	General View		Load JPG	☒
18	12/10/20 08:04	General View		Load JPG	☒
19	12/10/20 08:04	General View		Load JPG	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
20	12/10/20 08:04	General View	 Load JPG	☒
21	12/10/20 08:04	General View	 Load JPG	☒
22	12/10/20 08:04	General View	 Load JPG	☒
23	12/10/20 08:04	General View	 Load JPG	☒
24	12/10/20 08:04	General View	 Load JPG	☒
25	12/10/20 08:04	General View	 Load JPG	☒
26	12/10/20 08:04	General View	 Load JPG	☒
27	12/10/20 08:04	General View	 Load JPG	☒
28	12/10/20 08:04	General View	 Load JPG	☒
29	12/10/20 08:04	General View	 Load JPG	☒
30	12/10/20 08:04	General View	 Load JPG	☒
31	12/10/20 08:04	General View	 Load JPG	☒
32	12/10/20 08:04	General View	 Load JPG	☒
33	12/10/20 08:04	General View	 Load JPG	☒
34	12/10/20 08:04	General View	 Load JPG	☒
35	12/10/20 08:04	General View	 Load JPG	☒
36	12/10/20 08:04	General View	 Load JPG	☒
37	12/10/20 08:04	General View	 Load JPG	☒
38	12/10/20 08:04	General View	 Load JPG	☒
39	12/10/20 08:04	General View	 Load JPG	☒
40	12/10/20 08:04	General View	 Load JPG	☒
41	12/10/20 08:05	General View	 Load JPG	☒
42	12/10/20 08:05	General View	 Load JPG	☒
43	12/10/20 08:05	General View	 Load JPG	☒
44	12/10/20 08:05	General View	 Load JPG	☒
45	12/10/20 08:05	General View	 Load JPG	☒
46	12/10/20 08:05	General View	 Load JPG	☒
47	12/10/20 08:05	General View	 Load JPG	☒
48	12/10/20 08:05	General View	 Load JPG	☒
49	12/10/20 08:05	General View	 Load JPG	☒
50	12/10/20 08:05	General View	 Load JPG	☒
51	12/10/20 08:05	General View	 Load JPG	☒
52	12/10/20 08:05	General View	 Load JPG	☒
53	12/10/20 08:05	General View	 Load JPG	☒
54	12/10/20 08:05	General View	 Load JPG	☒
55	12/10/20 08:05	General View	 Load JPG	☒
56	12/10/20 08:05	General View	 Load JPG	☒
57	12/10/20 08:05	General View	 Load JPG	☒
58	12/10/20 08:05	General View	 Load JPG	☒
59	12/10/20 08:05	General View	 Load JPG	☒
60	12/10/20 08:05	General View	 Load JPG	☒
61	12/10/20 08:05	General View	 Load JPG	☒
62	12/10/20 08:05	General View	 Load JPG	☒
63	12/10/20 08:05	General View	 Load JPG	☒
64	12/10/20 08:05	General View	 Load JPG	☒
65	12/10/20 08:05	General View	 Load JPG	☒
66	12/10/20 08:05	General View	 Load JPG	☒
67	12/10/20 08:05	General View	Load JPG	☒

Assessment Reports			1 per page ▾	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
68	12/10/20 08:05	General View	 Load JPG	☒
69	12/10/20 08:05	General View	 Load JPG	☒
70	12/10/20 08:05	General View	 Load JPG	☒
71	12/10/20 08:05	General View	 Load JPG	☒
72	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
73	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
74	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
75	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
76	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
77	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
78	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
79	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
80	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
81	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
82	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
83	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
84	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
85	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
86	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
87	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
88	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
89	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
90	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
91	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
92	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
93	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
94	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
95	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
96	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
97	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
98	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
99	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
100	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
101	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
102	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
103	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
104	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
105	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
106	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
107	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
108	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
109	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
110	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
111	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
112	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
113	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
114	12/10/20 08:07	Reinspection Photo	 Load JPG	☒
115	12/10/20 08:07	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	✓
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
116	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
117	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
118	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
119	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
120	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
121	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
122	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
123	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
124	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
125	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
126	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
127	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
128	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
129	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
130	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
131	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
132	12/10/20 08:07	Reinspection Photo	 Load JPG	✓
133	12/10/20 08:07	After Repair Photo	 Load JPG	✓
134	12/10/20 08:07	After Repair Photo	 Load JPG	✓
135	12/10/20 08:07	After Repair Photo	 Load JPG	✓
136	12/10/20 08:07	After Repair Photo	 Load JPG	✓

Linked Accident Report Documents

Assessment Reports			1 per page	✓
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	24/09/20 15:46	Accident Statement	 Load HTM	
Photos/Images			3 per page	✓
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	24/09/20 15:43	Driving License	 Load JPG	✓
2	24/09/20 15:43	Insurance Cert	 Load JPG	✓
3	24/09/20 15:43	Accident Photo	 Load JPG	✓
4	24/09/20 15:43	Accident Photo	 Load JPG	✓
5	24/09/20 15:43	Accident Photo	 Load JPG	✓
6	24/09/20 15:43	Accident Photo	 Load JPG	✓
7	24/09/20 15:43	Accident Photo	 Load JPG	✓
8	24/09/20 15:43	Accident Photo	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	24/09/20 15:39	Sketch Plan	 Load JPG	✓
2	24/09/20 15:39	Sketch Plan #2	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20010286/UYD3S2**Date:** 21/10/2020REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30461619055
Claimant Vehicle No :	SMK4497L	Insured Vehicle No :	GP9690G
Date of Loss:	23/09/2020	Nature of Claim:	TP
		Claim No:	SNM20D203515/C02/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK4497L	Engine No:	G4FGKU126912
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMKU894093
Reg. Date:	11/04/2019 (Man. Year: 2019)	Odometer:	27564 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,906.10	8,350.64	23,555.46	73.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,420.00	3,540.00	7,880.00	69.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,326.10	11,890.64	31,435.46	72.56
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	43,326.10	9,500.00	33,826.10	78.07
+ GST 7.00/7.00% (S\$)	3,032.83	665.00	2,367.83	78.07
Nett Amount (S\$)	46,358.93	10,165.00	36,193.93	78.07

INSPECTION

Date of Assignment:	05/10/2020	
Date Inspected:	25/09/2020 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	9.0 days	

10/21/2020

Adjuster Report

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2020)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK4497L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN MOULDING	Necessary	357.00 FL	*118.20 FL
2	1	*BOOTLID	Badly Dented	1,356.00 FL	*1,356.00 FL
3	1	*BOOTLID REVERSE CAMERA	Not Necessary	981.00 FL	*- FL
4	1	*BOOTLID REVERSE CAMERA GARNISH	Not Necessary	102.00 FL	*- FL
5	1	*BOOTLID LOGO (HYBRID)	Necessary	110.00 FL	*96.00 FL
6	1	*BOOTLID EMBLEM (AVANTE)	Necessary	105.00 FL	*48.00 FL
7	2	*BOOTLID LAMP (L+R)	N/s Cracked / O/s Scratched	1,072.00 FL	*569.80 FL
8	1	*BOOTLID LOCK	Bent / Twisted	297.00 FL	*116.00 FL
9	1	*BOOTLID LOCK CATCH	Not Necessary	120.00 FL	*- FL
10	1	*BOOTLID INNER TRIM	Not Necessary	433.00 FL	*- FL
11	1	*BOOTLID HINGE (L+R)	N/s Bent	326.00 FL	*145.00 FL
12	2	*BOOTLID STOPPER (L+R)	Not Necessary	48.00 FL	*- FL
13	1	*BOOTLID WEATHERSTRIP	Twisted	373.00 FL	*182.00 FL
14	2	*TAIL LAMP (L+R)	N/s Broken / O/s Scratched	1,652.00 FL	*1,302.40 FL
15	1	*TAIL LAMP PANEL (L+R)	N/s Bent / O/s Repair	760.00 FL	*245.50 FL
16	1	*REAR BUMPER	Distorted	1,297.00 FL	*451.00 FL
17	1	*REAR BUMPER RETAINER (L+R)	N/s Cracked	312.00 FL	*45.00 FL
18	1	*REAR BUMPER REINFORCEMENT BAR	Cracked	781.00 FL	*455.00 FL
19	1	*REAR BUMPER BRACKET (L+R)	N/s Dented	522.00 FL	*155.00 FL
20	1	*REAR BUMPER SPONGE	Not Fitted	368.00 FL	*- FL
21	2	*REAR BUMPER CARPLATE LAMP (L+R)	Not Necessary	158.00 FL	*- FL
22	1	*REAR BUMPER CENTER GARNISH	Distorted	517.00 FL	*354.00 FL
23	1	*REAR BUMPER REFLECTOR (L+R)	N/s Cracked	876.00 FL	*255.20 FL
24	1	*REAR BUMPER UNDERCOVER	Deformed / Twisted	630.00 FL	*182.30 FL
25	1	*REAR FENDER (L+R)	N/s Buckled / O/S Repair	5,526.00 FL	*1,768.00 FL
26	1	*REAR FENDER PETROL COVER (LH)	Not Necessary	125.00 FL	*- FL
27	1	*REAR FENDER INNER TRIM (L+R)	N/s Deformed / Warped	1,762.00 FL	*266.20 FL
28	1	*REAR FENDER AIR VENT (L+R)	N/s Cracked	316.00 FL	*68.50 FL
29	1	*REAR FENDER COWLING (L+R)	N/s Deformed / Torn	562.00 FL	*166.20 FL
30	1	*END PANEL	Badly Dented	985.00 FL	*454.00 FL
31	1	*END PANEL TOP GARNISH	Twisted	423.00 FL	*160.00 FL
32	1	*REAR SMART LOCK ANTENNA	Not Necessary	815.00 FL	*- FL
33	1	*SPARE WHEEL PANEL	Repair	1,455.00 FL	*- FL
34	1	*SPARE WHEEL PANEL TOP BOARD	Warped	612.00 FL	*485.00 FL
35	1	*EXHAUST PIPE	Not Necessary	975.00 FL	*- FL
36	1	*EXHAUST GASKET	Not Necessary	128.00 FL	*- FL
37	2	*EXHAUST BRACKET (L+R)	Not Necessary	262.00 FL	*- FL
38	1	*EXHAUST HEAT SHIELD	Not Necessary	353.00 FL	*- FL
39	1	*REAR WINDSCREEN SEALANT	Necessary	250.00 FS	*40.00 FS
40	1	*SET BOOT LID INNER TRIM CLIPS	Necessary	100.00 FS	*40.00 FS
41	1	*REAR CARPLATE	Bent	150.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*REAR CARPLATE FRAME }		120.00 FS	*- FS
43	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
44	2		*REAR FENDER SEALANT	Not Necessary	800.00 FS	*- FS
45	20		*REAR FENDER INNER TRIM CLIPS (L+R)	Not Necessary	200.00 FS	*- FS
46	20		*REAR FENDER COLWING CLIPS (L+R)	Not Necessary	200.00 FS	*- FS
47	1		*END PANEL SEALANT	Necessary	250.00 FS	*50.00 FS
48	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	350.00 FS	*- FS
49	2		*SET REAR TYRE	Not Necessary	2,000.00 FS	*- FS
50	1		*REAR BUMPER REVERSE SENSOR	Shorted	882.00 FS	*200.00 FS
51	1		*BOOTLID LOCK COVER	Twisted	283.00 FL	*80.80 FL
52	1		*REAR BUMPER REINFORCEMENT BAR BRACKET (LH)	Repeated	279.00 FL	*- FL
53	1		*REAR BUMPER REFLECTOR WIRE HARNESS	Torn	1,035.00 FL	*388.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	34,851.00	10,333.30
- List Item Discount on L Items 10.00/20.00% (\$)	2,944.90	1,982.66
Total Parts (\$)	31,906.10	8,350.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGE PARTS, CUT / WELD, KNOCK & REALIGN.	New	3,600.00	1,800.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.	New	2,700.00	1,200.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA.	New	600.00	100.00
4	TO RNR REAR WINDSCREEN.	New	400.00	120.00
5	TO RNR REAR BOOT MECHANISM.	New	400.00	50.00
6	TO RNR, UPHOLSTERY, GARNISH AND ATTACHMENT PARTS.	New	1,200.00	80.00
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	New	200.00	50.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS.	New	450.00	0.00
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION. }	New	150.00	30.00
10	TO CHECK WIRING LAYOUT AND REAR BUMPER REFLECTOR FUNCTION. }	New	150.00	0.00
11	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	New	800.00	50.00
12	TO DO WATER LEAK TEST.	New	120.00	0.00
13	TO RNR FUEL TANK TO ASSIST WORK LOAD.	New	650.00	60.00
Gross Labour Cost (S\$)			11,420.00	3,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >