

TP ALG.
Denise.

GBF1151K.

Toyota Dyna 2982cc

KD72318024454.

Rear Number Plate	{ NH M	30(SN) X
Rear Number Plate Bracket		175.20 X
Rear Step Bracket. Bent		250(SN) 180(SN)
Rear Cross Member. NH M		748.10. X
Taillamp x 02 LH and RH set		$285.3 \times 2 = 570.60$ ✓
Taillamp Panel x 02 LH Bent		119.30. $119.3 \times 2 = 238.60$.
Tailgate Dented		1588 ✓
Tailgate Hinge x 04 2 pieces Bent		152.40. $76.2 \times 4 = 304.80$
Tailgate Side Lock x 02 LH Bent		$98.1 \times 2 = 196.20$ 98.10
Tailgate Lower Panel Reps		545.10 X.
Tailgate Lower Panel Reflector x 02 LH ut		65. 65 x 2 = 130
Toyota Sticker	{ NH	189. ✓
70km/h Sticker		15(SN) ✓
13 Pax Sticker.		15(SN) ✓
Stopper x 02 LH ut		$46 \times 2 = 92$ 46
Stopper Bracket x 02 LH Bent		$237.6 \times 2 = 475.20$ 475.20
		237.60

GBF 1151K .

Tuikup lower Reflector x 02 ^{LIT} _{wt} 50 x 2 = ~~100~~ 50

Rees Tool Box Best

~~410.20~~ ✓

250 (50)

8273

Panel Beating

~~1000~~ 600

Spray Painting

~~1000~~ 450

Wiring

~~50~~ 30

To apply tuff coat

~~150~~ 80

hist: 3526.20

Labour: 1160

lin 25%: 2644.65

total: 4014.65

IN: 210

A/s: 3.2K

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

3.2K