



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2102636

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 15/04/2021
Reference CC4/FCI20010305/Qes3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLL 654H
Insured Veh. SHB 4731S
Claim No. D20003826MFSH
Policy No. D-20094921MFSH
Accident Date 20/09/2020
Inspection Date 01/10/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20010305/Qes3q2	
			Date: 15/04/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4731S	Veh. Inspected	SLL 654H	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20003826MFSH	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	25/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 320i 4DR	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WBAPG56050NM25454	Colour	SILVER	
Odometer	143583 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	LING LONG	6 mm	
L/H Front Tyre	225/40 R18	LING LONG	6 mm	
R/H Rear Tyre	225/40 R18	LING LONG	6 mm	
L/H Rear Tyre	225/40 R18	LING LONG	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/09/2020	Inspection Date	01/10/2020	
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 654H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CRUMPLED	1,336.80	1,250.00
2	REAR BUMPER SIDE RETAINER (LH/RH) @\$47.65	SERVICEABLE	95.30	-
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER LOWER GARNISH	CRUMPLED	169.80	169.80
1	REAR BUMPER TOWING COVER	SCRATCHED	46.95	46.95
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	460.85	-
1	REAR BUMPER SPONGE	SERVICEABLE	150.20	-
2	REAR REVERSE SENSOR @\$238.05	SHORTED	476.10	450.00
1	REAR BUMPER CENTER BRACKET (ADDITIONAL)	CRACKED	50.20	50.20
	LESS 5% DISCOUNT		-141.81	-100.85
			2,694.39	1,916.10
	<u>LABOUR</u>			
	TO DISMANTLE & CHARGE REAR BUMPER ,REAR REINFORCEMENT ,KNOCLING REAR END PANEL AND ALL AREA AFFECTED BY ACCIDENT .		800.00	300.00
	TO PERFORM WIRE CHECKING .		20.00	20.00
	TO SPRAY REAR BUMPER, REAR REINFORCEMENT ,REAR END PAEL AND AFFECTED AREA.		800.00	300.00
			1,620.00	620.00
	GRAND TOTAL		4,314.39	2,536.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00

Report Ref No. CC4/FCI20010305/Qes3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 654H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 654H

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

